



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

# Notices to Mariners

**Edition No. 03/2021**  
**March 26, 2021**



Safety First, Service Always

## Monthly Eastern Edition

Canada 

Notices to Mariners – Monthly Eastern Edition  
Edition No. 03/2021

Aussi disponible en français :  
Avis aux navigateurs – Édition mensuelle de l'Est  
Édition n° 03/2021

**Published under the Authority of:**

Canadian Coast Guard Programs  
Aids to Navigation and Waterways  
Fisheries and Oceans Canada  
Montreal, QC H2Y 2E7

For more information, contact [Notmar.XNCR@dfo-mpo.gc.ca](mailto:Notmar.XNCR@dfo-mpo.gc.ca).

© Her Majesty the Queen in Right of Canada,  
as represented by the Minister of Fisheries, Oceans  
and the Canadian Coast Guard, 2021.

Cat. No. Fs152-5E-PDF (Electronic PDF, English)  
ISSN 1719-7678

Cat. No. Fs152-5F-PDF (Electronic PDF, French)  
ISSN 1719-7694

A web version is available here:

<https://www.notmar.gc.ca/monthly-mensuel-en.php> (English)

<https://www.notmar.gc.ca/monthly-mensuel-fr.php> (French)

## Explanatory Notes – Notices to Mariners (NOTMAR)

**Geographical positions** refer directly to the graduations of the largest scale Canadian Hydrographic Service chart (unless otherwise indicated).

**Bearings** refer to the true compass and are measured clockwise from 000° (North) clockwise to 359°; those relating to lights are from seaward.

**Visibility** of lights is that in clear weather.

**Depths** - The units used for soundings (metres, fathoms or feet) are stated in the title of each chart.

**Elevations** are normally given above Higher High Water, Large Tide (unless otherwise indicated).

**Distances** may be calculated as follows:

1 nautical mile = 1,852 metres (6,076.1 feet)

1 statute mile = 1,609.3 metres (5,280 feet)

1 metre = 3.28 feet

### Temporary and Preliminary Notices to Mariners – Section 1A of *Notices to Mariners*

These notices are indicated by a (T) or a (P), respectively. Please note that nautical charts are not amended by the Canadian Hydrographic Service for temporary (T) and preliminary (P) notices. It is recommended that mariners chart these corrections in pencil. For the list of charts affected by (T) & (P) notices, please refer to the current [Notices to Mariners - Monthly Summary of Temporary and Preliminary Notices](#) publication.

Please note: In addition to the temporary and preliminary changes normally advertised as (T) & (P) notices, there are a few permanent changes to aids to navigation that have been advertised as preliminary Notices to Mariners while charts are being updated for new editions.

### Marine Information Report and Suggestion Sheet

Mariners are requested to notify the responsible authorities when new or suspected dangers to navigation are discovered, changes observed in aids to navigation or corrections to publications are seen to be necessary. Such communications can be made using the [“Marine Information Report and Suggestion Sheet”](#) (fillable PDF form) and is inserted on the last page of each monthly edition of *Notices to Mariners*.

### NOTMAR Website – Monthly Editions, Chart Corrections and Chart Patches

The NOTMAR website allows users to access the [monthly publications](#), [chart corrections](#), and [chart patches](#).

Users can subscribe for free to the [email notification service](#) to receive notifications when charts of interest are updated, including their patches, as well as when a new monthly edition becomes available online.

In addition, the monthly publication and related files to download, such as chart patches and *Sailing Directions* diagrams, can be obtained all together through the download of a single ZIP file.


## Explanatory Notes – Canadian Hydrographic Service (CHS)

### Chart Corrections – Section 2 of *Notices to Mariners*

Corrections to nautical charts will be listed in numerical order by chart number. Each chart correction listed applies only to that particular chart. Related charts, if any, will have their own specific correction listed separately.

Users should also refer to CHS *Chart 1: Symbols, Abbreviations and Terms* for additional information pertaining to the correction of charts.

The illustration below describes the elements that will comprise a typical Section 2 chart correction:



The last correction number is identified with the **LNMD** or **Last Notice to Mariners Number / Date**.

Mariners are advised that only the most critical changes that directly affect safety to navigation are issued in “Section 2 – Chart Corrections.” This limitation is required to ensure that charts remain as clear and easy to read as possible. As a result, mariners may see minor discrepancies of a non-critical nature between information in official publications. For example, a small change in the nominal range or focal height of a light may not result in the production of a chart correction in *Notices to Mariners*, but may result in a correction in the [List of Lights, Buoys and Fog Signals](#) publication.

**Note:** In the case of a discrepancy between information provided on CHS charts relating to aids to navigation, and the *List of Lights, Buoys and Fog Signals* publication, the latter shall be deemed as containing the most up-to-date information.

### Canadian Nautical Charts & Publications

A source list of Canadian nautical charts and publications is published in Notice No. 14 of the *Notices to Mariners Annual Edition 2020*. The source supply and the prices effective at the time of printing are listed. For current chart edition dates, please refer to the following website: [www.chs-shc.gc.ca/charts-cartes/paper-papier/index-eng.asp](http://www.chs-shc.gc.ca/charts-cartes/paper-papier/index-eng.asp).

## Explanatory Notes – Marine Communications and Traffic Services (MCTS)

### Navigational Warnings / Notices to Shipping

The Canadian Coast Guard (CCG) is implementing a number of changes to the aids to navigation system in Canada.

These changes are advertised as Navigational Warnings, formerly called Notices to Shipping<sup>1</sup>, that are broadcast by the CCG, and are then followed up with Notices to Mariners, then charts are updated by hand correction, reprints or new editions.

Mariners are advised that all relevant Navigational Warnings (NAVWARNs) should be kept until superseded by Notices to Mariners or through revised charts issued by the Canadian Hydrographic Service (CHS).

NAVWARNs are accessible on the applicable regional page on the CCG Navigational Warnings website at <http://nis.ccg-gcc.gc.ca>.

CHS is reviewing the impact of these changes with CCG and together are preparing an action plan on the issuing of chart revisions.

For further information, contact your regional NAVWARN Issuing Desk.

<p><b>Atlantic Region (North)</b> <b>*Port aux Basques MCTS Centre</b></p> <p>“N” Series NAVWARNs</p> <p>Canadian Coast Guard 49 Stadium Rd. P.O. Box 99 Port aux Basques, NL A0M 1C0</p> <p>Telephone: 709-695-2168 or 1-800-563-9089 Facsimile: 709-695-7784</p> <p>Email: <a href="mailto:NAVWARN.MCTSPortAuxBasques@innav.gc.ca">NAVWARN.MCTSPortAuxBasques@innav.gc.ca</a></p>	<p><b>Central Region</b> <b>*Prescott MCTS Centre</b></p> <p>“Q” and “C” Series NAVWARNs</p> <p>Canadian Coast Guard 401 King Street West P.O. Box 1000 Prescott, ON K0E 1T0</p> <p>Telephone: 613-925-0666 Facsimile: 613-925-4519</p> <p>Email: <a href="mailto:NAVWARN.MCTSPrescott@innav.gc.ca">NAVWARN.MCTSPrescott@innav.gc.ca</a></p>
<p><b>Atlantic Region (South)</b> <b>*Sydney MCTS Centre</b></p> <p>“M” Series NAVWARNs</p> <p>Canadian Coast Guard 1190 Westmount Road Sydney, NS B1R 2J6</p> <p>Telephone: 902-564-7751 or 1-800-686-8676 Facsimile: 902-564-7662</p> <p>Email: <a href="mailto:NAVWARN.MCTSSydney@innav.gc.ca">NAVWARN.MCTSSydney@innav.gc.ca</a></p>	<p><b>Arctic Region</b> <b>*Iqaluit MCTS Centre</b></p> <p><i>Operational from approximately mid-May until late December.</i></p> <p>“A” and “H” Series NAVWARNs</p> <p>Canadian Coast Guard P.O. Box 189 Iqaluit, NU X0A 0H0</p> <p><u>“A” Series NAVWARNs</u> Telephone: 867-979-5269</p> <p><u>“H” Series NAVWARNs</u> Telephone: 867-979-0310 Facsimile: 867-979-4264</p> <p>Email: <a href="mailto:NAVWARN.MCTSIqaluit@innav.gc.ca">NAVWARN.MCTSIqaluit@innav.gc.ca</a></p>

\*Service available in English and in French.

<sup>1</sup> The expression “Notice to Shipping” was changed to “Navigational Warning” in January 2019.

## Table of Contents

<b>Section 1: General and Safety Information</b>	<b>1</b>
Canadian Coast Guard Publication – Comments and Suggestions on Notices To Mariners (NOTMAR) Publications .....	1
Transport Canada – COVID-19 Measures, Updates and Guidance.....	1
Canadian Hydrographic Service – Canadian Tide and Current Tables – Printing to be Discontinued ..	1
Canadian Hydrographic Service – Chart 1 – Printing to be Discontinued .....	1
Canadian Hydrographic Service – Notices to Mariners for Changes in Buoy Shape.....	2
*301/21 Canadian Hydrographic Service – Nautical Charts.....	2
*302/21 Canadian Hydrographic Service – Electronic Navigational Charts.....	2
*303/21 Canadian Hydrographic Service – Raster Digital Charts (BSB V3).....	3
*304/21 Transport Canada – Ship Safety Bulletin #03/2021 .....	3
*305/21 Canadian Coast Guard Publication - Amendments to the Notices to Mariners Annual Edition 2021 - Section A6, Notice 13: Navigation Safety Regulations, 2020, and Provisional List of Charts.....	3
*306/21 Canadian Coast Guard Publication - Amendments to the Notices to Mariners Annual Edition 2021 - Section F, Notice 35: Firing Practices and Exercise Areas .....	5
*307/21 Port Severn to/à Parry Sound – Unlit Buoys Permanently Established.....	5
<b>Section 1A: Temporary and Preliminary Notices</b>	<b>6</b>
Reminder – Comment Period for Active Preliminary Notices .....	6
*308(P)/21 Hamilton Sound: Eastern Portion / Partie-est – Notice of Proposed Changes .....	7
*309(P)/21 Garia Bay and / et Le Moine Bay – Light Buoy to be Discontinued.....	7
*310(P)/21 Port aux Basques and Approaches/et les Approches – Light Buoy to be Discontinued..	7
*311(P)/21 Hawkes Bay, Port Saunders, Back Arm – Notice of Proposed Changes.....	8
*312(P)/21 Garia Bay to / à Burgeo – Light Buoy to be Discontinued .....	8
*313(P)/21 Burgeo and / et Ramea Islands – Notice of Proposed Changes.....	8
*314(P)/21 Carmanville to / à Bacalhoa Island and / et Fogo – Light Buoy to be Discontinued .....	9
*315(P)/21 St. Lewis Sound and / et Inlet – Light Buoy to be Established .....	9
*316(P)/21 Epinette Point to/à Terrington Basin – Light Buoy to be Discontinued.....	9
*317(P)/21 Alexis Bay and / et Alexis River – Notice of Proposed Changes.....	10
*318(T)/21 Pointe des Monts aux/to Escoumins – Scientific Moorings .....	10
*319(P)/21 Sydney Harbour – Notice of Proposed Changes.....	11
*320(P)/21 Pictou Harbour and East River of Pictou – Notice of Proposed Changes.....	12
<b>Section 2: Chart Corrections</b>	<b>13</b>

---

**Section 3: Radio Aids to Marine Navigation Corrections 33**

\*321/21 Radio Aids to Marine Navigation 2021 (Atlantic, St. Lawrence, Great Lakes, Lake Winnipeg, Arctic and Pacific)..... 33

---

**Section 4: Sailing Directions and Small Craft Guide Corrections 36**

---

**Section 5: List of Lights, Buoys and Fog Signals Corrections 41**

## Numerical Index of Canadian Charts Affected

This numerical index lists all nautical charts mentioned in this monthly edition of Notices to Mariners. Only charts appearing in Section 2 of this publication require a chart correction. The appearance of charts in all other sections, particularly those related to the correction of other nautical publications, is included here for reference.

Chart No.	Pages	Chart No.	Pages	Chart No.	Pages
1220	<a href="#">44</a>	4416	<a href="#">25</a>	5179	<a href="#">10</a>
1234	<a href="#">13</a>	4426	<a href="#">25, 43, 44</a>	8014	<a href="#">32</a>
1236	<a href="#">10</a>	4473	<a href="#">2</a>	8048	<a href="#">32</a>
1314	<a href="#">13, 14</a>	4485	<a href="#">25, 44</a>	14853 (U.S.)	<a href="#">45</a>
1316	<a href="#">14</a>	4498	<a href="#">25, 26, 27</a>		
1430	<a href="#">15, 44</a>	4530	<a href="#">7</a>		
1432	<a href="#">15, 45</a>	4639	<a href="#">7</a>		
1433	<a href="#">15</a>	4641	<a href="#">7</a>		
1435	<a href="#">15</a>	4679	<a href="#">8</a>		
1436	<a href="#">16</a>	4701	<a href="#">41</a>		
1437	<a href="#">16</a>	4702	<a href="#">27</a>		
1552	<a href="#">16</a>	4722	<a href="#">38</a>		
2202	<a href="#">5</a>	4725	<a href="#">38, 39</a>		
3234	<a href="#">37</a>	4728	<a href="#">38, 39, 40</a>		
3395	<a href="#">37</a>	4731	<a href="#">27</a>		
4013	<a href="#">16</a>	4824	<a href="#">8</a>		
4017	<a href="#">16</a>	4825	<a href="#">8</a>		
4026	<a href="#">44</a>	4827	<a href="#">28</a>		
4049	<a href="#">16</a>	4830	<a href="#">28</a>		
4118	<a href="#">42</a>	4846	<a href="#">28</a>		
4140	<a href="#">42</a>	4855	<a href="#">41</a>		
4211	<a href="#">17</a>	4862	<a href="#">9</a>		
4233	<a href="#">17, 18, 42</a>	4911	<a href="#">28, 29</a>		
4240	<a href="#">19</a>	4912	<a href="#">29, 30</a>		
4266	<a href="#">11</a>	4913	<a href="#">30, 43</a>		
4276	<a href="#">43</a>	4920	<a href="#">43</a>		
4281	<a href="#">19, 20, 21, 43</a>	4938	<a href="#">12</a>		
4301	<a href="#">21, 22</a>	4956	<a href="#">30, 31</a>		
4302	<a href="#">22</a>	4968	<a href="#">2</a>		
4321	<a href="#">22, 23</a>	5031	<a href="#">6, 9</a>		
4335	<a href="#">23</a>	5032	<a href="#">6, 31, 41</a>		
4379	<a href="#">24, 42</a>	5143	<a href="#">38, 39</a>		
4381	<a href="#">42</a>	5162	<a href="#">38</a>		
4384	<a href="#">42</a>	5163	<a href="#">38</a>		
4395	<a href="#">24</a>	5164	<a href="#">38, 39</a>		
4406	<a href="#">24, 25</a>	5165	<a href="#">9, 38, 39, 40, 41</a>		



## Section 1: General and Safety Information

---

### Canadian Coast Guard Publication – Comments and Suggestions on Notices To Mariners (NOTMAR) Publications

In an effort to continuously improve the Notices to Mariners publications and to provide the most efficient service possible, the Notices to Mariners team invites all mariners and other interested parties to submit comments and suggestions on possible improvements to its various publications and services at the following email address: [Notmar.XNCR@dfo-mpo.gc.ca](mailto:Notmar.XNCR@dfo-mpo.gc.ca).

### Transport Canada – COVID-19 Measures, Updates and Guidance

(Recurrent publication of notice \*401/20, originally published in the *Notices to Mariners – Monthly Eastern Edition 04/2020* publication.)

Please refer to the link below for the latest updates to transportation related measures taken by Transport Canada in response to the evolving novel Coronavirus disease (COVID-19):

<https://www.tc.gc.ca/en/initiatives/covid-19-measures-updates-guidance-tc.html>.

For travel advice and all other updates, please visit: [Canada.ca/coronavirus](https://Canada.ca/coronavirus).

### Canadian Hydrographic Service – Canadian Tide and Current Tables – Printing to be Discontinued

(Recurrent publication of notice \*904/20, originally published in the *Notices to Mariners – Monthly Eastern Edition 09/2020* publication.)

Due to the availability of the *Canadian Tide and Current Tables* as [viewable and printable PDF files](#) on [charts.gc.ca](https://charts.gc.ca) for each complete volume and [additional information in different formats](#) (predictions, observations in tables, and graphics) on [tides.gc.ca](https://tides.gc.ca), the Canadian Hydrographic Service is permanently discontinuing the printing of all volumes of *Canadian Tide and Current Tables* starting January 2021.

Advances in technology bring a new era of marine navigation with a focus on digital and electronic products. The Canadian Hydrographic Service is transforming the way it delivers quality data and services to clients, in a timely manner, to support decision-making.

For more information, visit [www.charts.gc.ca](https://www.charts.gc.ca).

### Canadian Hydrographic Service – Chart 1 – Printing to be Discontinued

(Recurrent publication of notice \*905/20, originally published in the *Notices to Mariners – Monthly Eastern Edition 09/2020* publication.)

Due to the availability of *Chart 1: Symbols, Abbreviations and Terms* as both [viewable and printable PDF files](#) and [HTML](#) format on [charts.gc.ca](https://charts.gc.ca), the Canadian Hydrographic Service is permanently discontinuing the printing of *Chart 1: Symbols, Abbreviations and Terms* starting January 2021.

Advances in technology bring a new era of marine navigation with a focus on digital and electronic products. The Canadian Hydrographic Service is transforming the way it delivers quality data and services to clients, in a timely manner, to support decision-making.

For more information, visit [www.charts.gc.ca](https://www.charts.gc.ca).

## Canadian Hydrographic Service – Notices to Mariners for Changes in Buoy Shape

(Recurrent publication of notice \*906/20, originally published in the *Notices to Mariners – Monthly Eastern Edition 09/2020* publication.)

As part of the CHS Digital Transformation and for the sake of economy, CHS will no longer systematically issue Notices to Mariners (NTM) for buoy shape changes only. These changes will, however, be applied to electronic navigation charts (ENCs) where applicable. The paper and raster versions will be updated during the New Edition process.

### \*301/21 Canadian Hydrographic Service – Nautical Charts

Charts	Main Title	Scale	Published	Cat#	Price
<b>New Charts</b>					
4968	Îles Mack à/to La Tabatière	1:40 000	2021-03-26	1	\$20.00
<b>Charts Permanently Withdrawn</b>					
4473	Île de la Grande Passe aux/to Îles Bun	Cancelled by 4968			

### \*302/21 Canadian Hydrographic Service – Electronic Navigational Charts

S-57 ENC Number	Chart Title	ENC Compilation Scale	Published
<b>New Charts</b>			
CA273529 (Edn 1.000)	Viscount Melville Sound and/et M'clure Strait	1:150 000	2021-03-26
CA571037 (Edn 1.000)	Shields Bay (Part 1 of 3)	1:11 000	2021-03-26
CA571038 (Edn 1.000)	Shields Bay (Part 2 of 3)	1:11 000	2021-03-26
CA571039 (Edn 1.000)	Shields Bay (Part 3 of 3)	1:11 000	2021-03-26
CA576591 (Edn 1.000)	Lark Harbour and/et York Harbour	1:10 000	2021-03-26
CA576706 (Edn 1.000)	Wolf Cove	1:1 250	2021-03-12
<b>New Editions</b>			
CA270390 (Edn 5.000)	Queen Charlotte Sound to/à Dixon Entrance	1:262 500	2021-03-12
CA379151 (Edn 7.000)	Pointe de l'Est - Île d'Anticosti	1:36 000	2021-03-12
CA473475 (Edn 2.000)	Culbertson Island to/à Frobisher's Farthest	1:12 500	2021-03-26
CA473499 (Edn 2.000)	Rivière Koksoak	1:15 000	2021-03-05
CA479148 (Edn 6.000)	Port-Menier - Île d'Anticosti	1:24 000	2021-03-12
CA479152 (Edn 8.000)	Pointe de l'Ouest - Île d'Anticosti	1:24 000	2021-03-12
CA576372 (Edn 5.000)	Lumsden Harbour	1:10 000	2021-03-12
CA579219 (Edn 3.000)	Rivière-au-Tonnerre	1:2 500	2021-03-26
<b>Charts Permanently Withdrawn</b>			
CA570179	Wiah Point	Cancelled by CA571010, CA571011	
CA570404	Masset Harbour and Approches/et les Approches	Cancelled by CA571010, CA571011, CA571006, CA571007, CA571009, CA571005	
CA576696	Lark Harbour and/et York Harbour (Bay of Islands)	Cancelled by CA576591	

**\*303/21 Canadian Hydrographic Service – Raster Digital Charts (BSB V3)**

Charts	Main Title	Scale	Published
<b>Charts Permanently Withdrawn</b>			
RM-4473	Île de la Grande Passe aux/to Îles Bun		Cancelled by 4968

**\*304/21 Transport Canada – Ship Safety Bulletin #03/2021**

A new **Ship Safety Bulletin** has recently been posted on the Transport Canada website at [www.tc.gc.ca/ssb-bsn/](http://www.tc.gc.ca/ssb-bsn/).

To view or download this bulletin, please click on the links below:

**[SSB#03/2021](#) – Updated guidance to vessel crew members and non-crew marine sector workers respecting entry into Canada  
RDIMS#17324363**

Sign up for [e-Bulletin](#) to receive an e-mail notice each time a new Ship Safety Bulletin is published on our website.

Contact us at [marinesafety-securitemaritime@tc.gc.ca](mailto:marinesafety-securitemaritime@tc.gc.ca) or 1-855-859-3123 (Toll Free).

**\*305/21 Canadian Coast Guard Publication - Amendments to the Notices to Mariners Annual Edition 2021 - Section A6, Notice 13: Navigation Safety Regulations, 2020, and Provisional List of Charts**

**Page 1:**

**AMEND AS FOLLOWS:**

As the publications required by the **CNPR NSR 2020** must be on board, simply being able to access the publications through the internet would not be considered on board and therefore not acceptable. However, publications downloaded and saved on board or hard copies printed from official internet sources would be acceptable.

**Page 2:**

**AMEND AS FOLLOWS:**

**PROVISIONAL LIST OF CHARTS**

- 1 This list is issued for reference in conjunction with the ~~Charts and Nautical Publications Regulations, 1995~~ **Navigation Safety Regulations (2020)** to assist mariners navigating Canadian waters or Fishing Zones when proceeding to or from the ports indicated. It is also used by Transport Canada, Marine Safety and Security Inspectors in enforcing primarily by spot checks the *Navigation Safety Regulations (2020)* and when conducting Port State control inspections.

**Page 6:**

**ADD AS FOLLOWS :**

**4. Arriving Corner Brook, Nfld., by Routes in Lists 1, 2 or 3**

Charts in List 3, or List 1 up to 4002, or List 2 up to 4023 plus 4022, and then:

CANADIAN CATALOGUE				U.K. CATALOGUE
Chart	ENC	Title	Scale 1:	Chart
...	...	...	...	...
4652	CA576185	Humber Arm, Meadows Point to/à Humber River	14,600	4741
	CA576185	Corner Brook	7,200	

**Page 17:**

**ADD AS FOLLOWS :**

**25. Arriving Vancouver, British Columbia (continued)**

CANADIAN CATALOGUE				U.S.A CATALOGUE	U.K. CATALOGUE
Chart	ENC	Title	Scale 1:	Chart	Chart
...	...	...	...	...	...
3496	CA570747	Approaches to/Approches à Vancouver Harbour	12,000		4966

**Page 20:**

**ADD AS FOLLOWS :**

**33. Inner Passages, British Columbia, Vancouver to Portland Canal**

CANADIAN CATALOGUE				U.K. CATALOGUE
Chart	ENC	Title	Scale 1:	Chart
...	...	...	...	...
3496	CA570747	Approaches to/Approches à Vancouver Harbour	12,000	4966

**\*306/21 Canadian Coast Guard Publication - Amendments to the Notices to Mariners  
Annual Edition 2021 - Section F, Notice 35: Firing Practices and Exercise Areas**

**Page 35:**

**AMEND AS FOLLOWS:**

Additional information on active range hours or for safe transit through the area may be obtained from:

- a. Winchelsea Island Control at 1-888-221-1011 (next day's activity only);
- b. CFMETR Range Officer at 250-468-5002 (long range planning);
- c. Winchelsea Island Control VHF CH 10 or 16 (for safe transit area information when approaching Area "WG"). or
- d. CMB VHF 21B or Weather 3 (listen only, for active times).
- e. ~~Notice to Shipping, Victoria MCTS Centre, at 250-363-8904; email: [mcts@pac.dfo-mpo.gc.ca](mailto:mcts@pac.dfo-mpo.gc.ca)~~  
Navigational Warning. Prince Rupert MCTS Centre at 250-627-3070.  
[NAVWARN.MCTSPrinceRupert@innav.gc.ca](mailto:NAVWARN.MCTSPrinceRupert@innav.gc.ca)
- f. Victoria MCTS Centre at 250-363-6333.

**\*307/21 Port Severn to à Parry Sound – Unlit Buoys Permanently Established**

Reference Chart: 2202

The following unlit buoys have been permanently established:

Aid Name	LL #	Position
Unlit buoy C1	8042.1	44° 48' 10.6"N 079° 43' 13.7"W
Unlit buoy C2	8042.12	44° 48' 09.8"N 079° 43' 15.4"W
Unlit buoy C3	8042.15	44° 48' 08.6"N 079° 43' 13.7"W

(D2021-001, 003, 004)

## Section 1A: Temporary and Preliminary Notices

### Reminder – Comment Period for Active Preliminary Notices

This is a reminder that the comment period is still open for the following active Preliminary notices:

Notice #	Reference Chart #	Aids Affected (LL #)	Intent of Notice
<b>Newfoundland and Labrador Coast</b>			
109(P)/21	5031	276.9	Light to be Discontinued
110(P)/21	5032	279.9	Notice of Proposed Changes

Please refer to the [Notices to Mariners - Monthly Summary of Temporary and Preliminary Notices](#) publication for details.

### Newfoundland and Labrador Coast

#### Temporary Notices

No notices applicable for this edition.

#### Preliminary Notices

##### Atlantic Region

##### Comment Submission

Comments on proposed changes in preliminary (P) notices are solicited from mariners and other interested parties within three months of the initial publication date. Following this date, the notices will be cancelled. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

Comments should be directed to the following:

Superintendent,  
Aids to Navigation & Waterways  
Canadian Coast Guard, Atlantic Region  
P.O. Box 1236  
Charlottetown, PE C1A 7M8  
Telephone: (902) 566-7936  
Email: [claire.maclaren@dfo-mpo.gc.ca](mailto:claire.maclaren@dfo-mpo.gc.ca)

**\*308(P)/21 Hamilton Sound: Eastern Portion / Partie-est – Notice of Proposed Changes**

Reference chart: 4530

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

Aid Name	LL #	Position	Proposed Changes
Stag Harbour Run light buoy DX	372.6	49° 34' 07.7"N 054° 15' 55.5"W	Establish an East cardinal buoy equipped with a white lantern with flash characteristics: Q(3) 10 s.
Stag Harbour Run light buoy DX7	372.61	49° 33' 37.2"N 054° 16' 29.1"W	Establish a port hand buoy equipped with a green lantern with flash characteristics: Fl 0.5 s, Ec 3.5 s.
Carmanville light buoy DC13	390.131	49° 23' 34.9"N 054° 16' 54.6"W	Change the function of the buoy from port to isolated danger. Change lantern colour from green to white and flash characteristics to: Fl (2) 5 s. Change the aid designator from DC13 to DC.

Initial publication date: Friday, March 26, 2021

[Comment submission deadline](#): Thursday, June 24, 2021

(N2021-013, 014, 047)

**\*309(P)/21 Garia Bay and / et Le Moine Bay – Light Buoy to be Discontinued**

Reference chart: 4639

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
Petites light and whistle buoy QT2	149.7	47° 36' 10.0"N 058° 39' 15.2"W

Initial publication date: Friday, March 26, 2021

[Comment submission deadline](#): Thursday, June 24, 2021

(N2021-020)

**\*310(P)/21 Port aux Basques and Approches/et les Approches – Light Buoy to be Discontinued**

Reference chart: 4641

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
Pikes Island Breakwater light buoy QP6	170.5	47° 34' 31.8"N 059° 07' 56.0"W

Initial publication date: Friday, March 26, 2021

[Comment submission deadline](#): Thursday, June 24, 2021

(N2021-015)

**\*311(P)/21 Hawkes Bay, Port Saunders, Back Arm – Notice of Proposed Changes**

Reference chart: 4679

The Canadian Coast Guard proposes to permanently change the following aid to navigation:

Aid Name	LL #	Position	Proposed Changes
Ardent Rock light buoy XP4	211.7	50° 43' 17.2"N 057° 20' 02.6"W	Reposition buoy to the following position: 50° 43' 17.3"N 057° 20' 01.2"W. Change flash characteristics to Fl 0.3 s, Ec 0.7 s.

Initial publication date: Friday, March 26, 2021

[Comment submission deadline](#): Thursday, June 24, 2021

(N2021-037)

**\*312(P)/21 Garia Bay to / à Burgeo – Light Buoy to be Discontinued**

Reference chart: 4824

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
South East Shoal East cardinal light buoy QES	145.88	47° 37' 58.5"N 058° 20' 44.8"W

Initial publication date: Friday, March 26, 2021

[Comment submission deadline](#): Thursday, June 24, 2021

(N2021-019)

**\*313(P)/21 Burgeo and / et Ramea Islands – Notice of Proposed Changes**

Reference chart: 4825

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

Aid Name	LL #	Position	Proposed Changes
Boar Rock light and bell buoy QG2	143	47° 35' 32.5"N 057° 33' 42.5"W	Change lantern colour from red to white and flash characteristics to: Fl (2) 5 s. Change the function of the buoy from starboard to isolated danger. Discontinue the bell.
Fish Island Rock light and bell buoy QG3	143.5	47° 37' 03.7"N 057 35' 06.9"W	Reduce the size of the buoy. Discontinue the bell.
Shoal Short Reach light buoy QG5.1	143.71	47° 37' 01.1"N 057° 36' 25.1"W	Reposition buoy to the following position: 47° 37' 01.4"N 057° 36' 26.6"W. Change flash characteristics to Fl 0.3 s, Ec 0.7 s.
Harbour Shoal light buoy QG5.3	143.74	47° 36' 49.4"N 057° 36' 25.5"W	Establish a port hand buoy equipped with a green lantern with flash characteristics: Fl 0.5 s, Ec 3.5 s.

Initial publication date: Friday, March 26, 2021

[Comment submission deadline](#): Thursday, June 24, 2021

(N2021-025, 026, 027, 029)



**\*314(P)/21 Carmanville to / à Bacalhoa Island and / et Fogo – Light Buoy to be Discontinued**

Reference chart: 4862

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
Noggin Cove light buoy DN2	388.1	49° 25' 01.8"N 054° 18' 38.6"W

Initial publication date: Friday, March 26, 2021

[Comment submission deadline](#): Thursday, June 24, 2021

(N2021-022)

**\*315(P)/21 St. Lewis Sound and / et Inlet – Light Buoy to be Established**

Reference chart: 5031

The Canadian Coast Guard proposes to permanently establish the following aid to navigation:

Aid Name	LL #	Position	Notes
Hussey Shoal light buoy NUB1	278.1	52° 17' 27.0"N 055° 35' 24.0"W	Establish a port hand buoy equipped with a green lantern with flash characteristics: Fl 0.5 s, Ec 3.5 s.

Initial publication date: Friday, March 26, 2021

[Comment submission deadline](#): Thursday, June 24, 2021

(N2021-048)

**\*316(P)/21 Epinette Point to/à Terrington Basin – Light Buoy to be Discontinued**

Reference chart: 5165

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
Blake Shoal light buoy H6	297.4	53° 34' 22.2"N 059° 56' 42.6"W

Initial publication date: Friday, March 26, 2021

[Comment submission deadline](#): Thursday, June 24, 2021

(N2021-017)

**\*317(P)/21 Alexis Bay and / et Alexis River – Notice of Proposed Changes**

Reference chart: 5179

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

Aid Name	LL #	Position	Proposed Changes
Red Point Bank light buoy NW1	270.4	52° 31' 21.7"N 055° 44' 21.7"W	Change the buoy function from port hand to East cardinal. Change flash characteristics to Q(3) 10 s. Change the aid designator from NW1 to NWW.
Mad Moll Rocks North Cardinal light buoy NA	270.45	52° 30' 28.8"N 055° 43' 51.0"W	Change the buoy function from North cardinal to port hand. Change flash characteristics to FI 0.5 s, Ec 3.5 s. Change the aid designator from NA to NA1/1.
Groves Island Tickle North light buoy NA8	271	52° 32' 22.9"N 056° 09' 21.5"W	Reduce the size of the buoy.
Groves Island Tickle South light buoy NA9	272	52° 32' 06.7"N 056° 09' 35.8"W	Reduce the size of the buoy.
Port Hope Simson light buoy NA13	272.7	52° 36' 26.7"N 056° 13' 41.3"W	Establish a port hand buoy equipped with a green lantern with flash characteristics: FI 0.5 s, Ec 3.5.

Initial publication date: Friday, March 26, 2021

[Comment submission deadline](#): Thursday, June 24, 2021

(N2021-044)

**Atlantic Coast**

**Temporary Notices**

**\*318(T)/21 Pointe des Monts aux/to Escoumins – Scientific Moorings**

Reference chart: 1236

Over 80 underwater scientific moorings have been placed in the area delimited by the following positions:

- Pt 1: 49° 18' 00.7"N 067° 40' 03.6"W
- Pt 2: 49° 18' 12.0"N 067° 43' 30.8"W
- Pt 3: 49° 17' 31.3"N 067° 43' 32.4"W
- Pt 4: 49° 17' 25.3"N 067° 40' 15.5"W

(NW-Q-0968-20)

## Preliminary Notices

### Atlantic Region

#### Comment Submission

Comments on proposed changes in preliminary (P) notices are solicited from mariners and other interested parties within three months of the initial publication date. Following this date, the notices will be cancelled. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

Comments should be directed to the following:

Superintendent,  
Aids to Navigation & Waterways  
Canadian Coast Guard, Atlantic Region  
P.O. Box 1236  
Charlottetown, PE C1A 7M8  
Telephone: (902) 566-7936  
Email: [claire.maclaren@dfo-mpo.gc.ca](mailto:claire.maclaren@dfo-mpo.gc.ca)

### **\*319(P)/21 Sydney Harbour – Notice of Proposed Changes**

Reference chart: 4266

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

Aid Name	LL #	Position	Proposed Changes
Sydney Northwest Bar light buoy S6	779	46° 12' 28.6"N 060° 14' 01.3"W	Reposition buoy to the following position: 46° 12' 27.0"N 060° 14' 04.4"W. Change flash characteristics to FI 0.3 s, Ec 0.7 s. Increase intensity of lantern. Change the aid designator.
Northwest Bar light buoy SD2	779.4	46° 12' 32.8"N 060° 14' 10.3"W	Discontinue buoy.
Barachois light buoy S14	785.5	46° 09' 32.8"N 060° 12' 53.0"W	Change the period of service from seasonal to year round.
Battery Point light buoy S15	786	46° 08' 53.5"N 060° 12' 26.5"W	Reposition buoy to the following position: 46° 08' 56.6"N 060° 12' 28.2"W. Increase intensity of lantern. Change the period of service from seasonal to year round.
Shingle Point light buoy S18	787	46° 08' 27.7"N 060° 12' 13.7"W	Change the period of service from seasonal to year round.
Cran Rock light buoy S2	789	46° 16' 25.6"N 060° 11' 29.1"W	Increase intensity of lantern.
Allen Point buoy SA8	5777.02	46° 11' 27.5"N 060° 15' 49.0"W	Add a red lantern with flash characteristics FI 0.5 s, Ec 3.5 s. Change the period of service from year round to seasonal.
Sydney River buoy S23	5777.04	46° 07' 18.5"N 060° 12' 38.0"W	Reduce the size of the buoy. Change the period of service from year round to seasonal.
Sydney River buoy S24	5777.05	46° 07' 21.5"N 060° 12' 51.5"W	Reduce the size of the buoy. Change the period of service from year round to seasonal.
South Bar South Cardinal buoy SS	5787.21	46° 12' 09.1"N 060° 13' 04.9"W	Add a white lantern with flash characteristics Q(6) + LFI 15 s.

Initial publication date: Friday, March 26, 2021

**Comment submission deadline:** Thursday, June 24, 2021

(G2021-019)

**\*320(P)/21 Pictou Harbour and East River of Pictou – Notice of Proposed Changes**

Reference chart: 4938

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

Aid Name	LL #	Position	Proposed Changes
Pictou light buoy SJ	900.5	45° 42' 10.0"N 062° 36' 45.0"W	Reposition buoy to the following position: 45° 42' 30.6"N 062° 36' 51.9"W.
Pictou Harbour light buoy SJ4	901	45° 41' 33.0"N 062° 38' 37.0"W	Reposition buoy to the following position: 45° 41' 34.8"N 062° 38' 33.0"W.
Pictou Harbour light buoy SJ5	901.1	45° 41' 27.9"N 062° 39' 01.2"W	Establish a port hand buoy equipped with a green lantern with flash characteristics: FI 0.5 s, Ec 3.5 s.
Murdock Shoal light buoy SJ6	901.6	45° 41' 27.3"N 062° 39' 30.7"W	Decrease intensity of lantern.
Pictou Landing light buoy SJ11	905	45° 40' 52.3"N 062° 40' 43.7"W	Reposition buoy to the following position: 45° 40' 55.8"N 062° 40' 34.2"W. Decrease intensity of lantern.
Pictou Harbour light buoy SJ12	905.2	45° 40' 51.5"N 062° 41' 30.5"W	Reposition buoy to the following position: 45° 40' 49.4"N 062° 41' 28.1"W. Change flash characteristics to FI 0.3 s, Ec 0.7 s.
Pictou Harbour light buoy SJ15	905.3	45° 40' 38.7"N 062° 41' 04.7"W	Reposition buoy to the following position: 45° 40' 38.6"N 062° 41' 00.1"W. Change flash characteristics to FI 0.3 s, Ec 0.7 s. Decrease intensity of lantern.
Hector Quay light buoy SJD	905.55	45° 40' 17.1"N 062° 42' 41.0"W	Establish an isolated danger buoy equipped with a white lantern with flash characteristics: FI (2) 5 s.
Pictou Landing Buoy SH2	5905.45	45° 40' 35.6"N 062° 41' 01.7"W	Establish an unlit starboard hand buoy .
Shipyard Point buoy SJ46	5910.6	45° 36' 50.7"N 062° 38' 48.2"W	Reposition buoy to the following position: 45° 36' 49.1"N 062° 38' 45.0"W.

Initial publication date: Friday, March 26, 2021

[Comment submission deadline](#): Thursday, June 24, 2021

(G2021-022)

**Inland Waters**

No notices applicable for this edition.

## Section 2: Chart Corrections

### 1234 - Port de Pointe-au-Pic - New Edition - 04-NOV-2011 - NAD 1983

12-MAR-2021

LN/M/D. 07-AUG-2020

Delete depth of 7 metres 6 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA579032  
47°37'19.9"N 070°08'23.6"W  
*DFO(6410570-01)*

Add depth of 8 metres 1 decimetre  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA579032  
47°37'20.1"N 070°08'23.9"W  
*DFO(6410570-02)*

### 1314 - Donnacona à/to Batiscan - New Edition - 15-MAR-2019 - NAD 1983

12-MAR-2021

LN/M/D. 06-MAR-2020

Add depth of 1 metre 6 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA479017  
46°32'06.4"N 072°10'49.7"W  
*DFO(6410536-01)*

Delete depth of 9 metres 5 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA479017  
46°38'58.1"N 071°45'23.7"W  
*DFO(6410536-02)*

Add depth of 9 metres 2 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA479017  
46°38'58.2"N 071°45'23.9"W  
*DFO(6410536-03)*

Add drying depth of 0 metres 8 decimetres  
(See Chart No. 1, I15)  
This notice affects Electronic Navigational Chart: CA479017  
46°40'58.2"N 071°52'25.8"W  
*DFO(6410536-05)*

Add depth of 8 metres 7 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA479017  
46°40'57.7"N 071°52'16.5"W  
*DFO(6410536-06)*

Delete depth of 6 metres 5 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA479017  
46°40'59.8"N 071°52'02.7"W  
*DFO(6410536-07)*

Add depth of 5 metres 2 decimetres  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA479017  
46°41'01.0"N 071°52'00.9"W  
*DFO(6410536-08)*

Add depth of 2 metres 1 decimetre  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA479017  
46°33'31.8"N 072°07'52.2"W  
*DFO(6410536-09)*

**1314 - Portneuf - New Edition - 15-MAR-2019 - NAD 1983**

12-MAR-2021

LNMD. 06-MAR-2020

Affix patch 46°40'57.3"N 071°52'41.6"W  
Download Patch - [https://www.notmar.gc.ca/chsftp/patches/1314\\_6410531\\_1\\_202102100834.pdf](https://www.notmar.gc.ca/chsftp/patches/1314_6410531_1_202102100834.pdf)  
This notice affects Electronic Navigational Chart: CA579019  
*DFO(6410531-01)*

**1316 - Port de Québec - New Edition - 03-APR-2020 - NAD 1983**

26-MAR-2021

LNMD. 15-JAN-2021

Add depth of 10 metres 0 decimetres 46°47'30.0"N 071°13'29.3"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA579003  
*DFO(6410559-01)*

Add depth of 6 metres 7 decimetres 46°47'52.8"N 071°12'49.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA579003  
*DFO(6410559-02)*

Delete depth of 11 metres 4 decimetres 46°49'27.8"N 071°11'59.3"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA579003  
*DFO(6410559-03)*

Add depth of 11 metres 0 decimetres 46°49'27.9"N 071°11'59.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA579003  
*DFO(6410559-04)*

Delete depth of 9 metres 1 decimetre 46°49'20.6"N 071°12'36.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA579003  
*DFO(6410559-05)*

Add depth of 8 metres 1 decimetre 46°49'20.9"N 071°12'36.3"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA579003  
*DFO(6410559-06)*

Delete depth of 7 metres 1 decimetre 46°49'20.2"N 071°12'44.4"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA579003  
*DFO(6410559-07)*

Add depth of 6 metres 5 decimetres 46°49'20.5"N 071°12'44.4"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA579003  
*DFO(6410559-08)*

Add depth of 4 metres 4 decimetres 46°49'26.4"N 071°12'38.1"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA579003  
*DFO(6410559-09)*

Affix patch 46°49'09.0"N 071°12'27.0"W  
Download Patch - [https://www.notmar.gc.ca/chsftp/patches/1316\\_6410582\\_1\\_202102231451.pdf](https://www.notmar.gc.ca/chsftp/patches/1316_6410582_1_202102231451.pdf)  
*DFO(6410582-01)*

**1430 - Lac Saint-Louis - New Edition - 23-NOV-2018 - NAD 1983**

19-MAR-2021

LNM/D. 21-AUG-2020

Add private light (Priv)F R 6m5M 45°19'26.6"N 073°54'58.7"W  
(See Chart No. 1, P1, P65)  
This notice affects Electronic Navigational Chart: CA479228  
(Q2020217) LL(32.1) DFO(6410520-01)

**1432 - Lac Saint-François/Lake St. Francis A-B - New Edition - 26-DEC-2014 - World Geodetic System 1984**

26-MAR-2021

LNM/D. 21-AUG-2020

Amend FY 9m to read FG 9m against light 45°07'39.8"N 074°24'34.1"W  
(See Chart No. 1, P16)  
DFO(6604744-02)

Delete orange and white mooring barrel buoy 45°11'28.4"N 074°19'15.9"W  
(See Chart No. 1, Q40)  
This notice affects Electronic Navigational Chart: CA473233  
DFO(6604745-01)

Delete private orange and white mooring spherical buoy 45°08'41.2"N 074°22'17.8"W  
(See Chart No. 1, Q40)  
This notice affects Electronic Navigational Chart: CA473233  
DFO(6604745-02)

**1432 - Lac Saint-François/Lake St. Francis B-C - New Edition - 26-DEC-2014 - World Geodetic System 1984**

26-MAR-2021

LNM/D. 21-AUG-2020

Amend FY 9m to read FG 9m against light 45°07'39.8"N 074°24'34.1"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA473233  
LL(111) DFO(6604744-01)

Delete private orange and white mooring can buoy 45°02'03.2"N 074°37'18.6"W  
(See Chart No. 1, Q40)  
This notice affects Electronic Navigational Chart: CA473233  
DFO(6604745-03)

**1433 - Île St-Régis to/à Croil Islands A-B - New Edition - 26-DEC-2014 - World Geodetic System 1984**

26-MAR-2021

LNM/D. 24-JUL-2020

Delete private orange and white mooring can buoy 45°02'03.2"N 074°37'18.6"W  
(See Chart No. 1, Q40)  
This notice affects Electronic Navigational Chart: CA473233  
DFO(6604745-03)

**1435 - Brockville Narrows - New Edition - 26-JUN-2015 - World Geodetic System 1984**

19-MAR-2021

LNM/D. 22-MAR-2019

Amend FI G 11m to read FI G 10m against light 44°33'33.8"N 075°42'53.5"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA473275, CA573388  
LL(329) DFO(6604723-01)

**1435 - Cardinal to/à Whaleback Shoal A-B - New Edition - 26-JUN-2015 - World Geodetic System 1984**

19-MAR-2021

LNM/D. 22-MAR-2019

Delete orange and white mooring spherical buoy, marked Or W 44°42'00.5"N 075°31'36.3"W  
(See Chart No. 1, Q40)  
This notice affects Electronic Navigational Chart: CA473275  
LL(7030.228) DFO(6604723-02)

**1436 - Whaleback Shoal to/au Summerland Group - New Edition - 17-MAR-2017 - World Geodetic System 1984**

12-MAR-2021 LNM/D. 22-MAR-2019

Add wreck WK with known depth of 24.4 metres 44°22'37.2"N 075°55'49.1"W  
(See Chart No. 1, K26)  
This notice affects Electronic Navigational Chart: CA473035  
DFO(6604722-01)

Delete orange and white mooring lighted spherical buoy FI Y, marked (Priv) 44°22'36.0"N 075°55'48.0"W  
(See Chart No. 1, Q41)  
This notice affects Electronic Navigational Chart: CA473035  
DFO(6604722-02)

**1437 - Summerland Group to/à Grindstone Island - New Edition - 27-JUL-2018 - World Geodetic System 1984**

12-MAR-2021 LNM/D. 05-OCT-2018

Add wreck WK with known depth of 24.4 metres 44°22'37.2"N 075°55'49.1"W  
(See Chart No. 1, K26)  
This notice affects Electronic Navigational Chart: CA473035  
DFO(6604722-01)

Delete orange and white mooring lighted spherical buoy FI Y, marked (Priv) 44°22'36.0"N 075°55'48.0"W  
(See Chart No. 1, Q41)  
This notice affects Electronic Navigational Chart: CA473035  
DFO(6604722-02)

**1552 - Portage-du-Fort to/à Chute du Grand Calumet including/y compris le chenal du Rocher Fendu - Sheet/Feuille 1 - New Edition - 23-FEB-2007 - NAD 1983**

12-MAR-2021

Amend vertical clearance of 53 feet, to read 45 feet 45°37'46.7"N 076°41'05.2"W  
(See Chart No. 1, D22)  
DFO(6604733-01)

**4013 - Halifax to / à Sydney - New Edition - 06-SEP-2002 - NAD 1983**

12-MAR-2021 LNM/D. 23-OCT-2020

Add depth of 1 foot 45°16'47.6"N 061°01'37.1"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA276204, CA376067, CA476675  
DFO(6309308-13)

**4017 - Cape Race to / à Cape Freels - New Edition - 07-MAR-2003 - NAD 1983**

19-MAR-2021 LNM/D. 15-MAR-2019

Add private yellow ODAS/SADO lighted pillar buoy FI(5) Y 20s, Priv 47°14'12.0"N 050°57'00.0"W  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA276101  
DFO(6309327-01)

**4049 - Grand Bank, Northern Portion / Grand Banc, Partie Nord to / à Flemish Pass / Passe Flamande - New Edition - 19-MAY-1995 - NAD 1983**

19-MAR-2021 LNM/D. 30-OCT-2020

Add private yellow ODAS/SADO lighted pillar buoy FI(5) Y 20s, Priv 47°14'12.0"N 050°57'00.0"W  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA276101  
DFO(6309327-01)



**4211 - Cape Lahave to / à Liverpool Bay - New Edition - 20-JUN-2003 - NAD 1983**

26-MAR-2021

LNM/D. 27-JUL-2018

Amend QG to read Iso G against light 44°01'09.4"N 064°39'45.9"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA376045, CA476202  
(F2021004) LL(408.2) DFO(6309357-01)

**4233 - Cape Canso to / à Country Island - New Chart - 11-JAN-1991 - NAD 1983**

12-MAR-2021

LNM/D. 19-FEB-2021

Add	drying height of 1.2 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA376067	45°21'18.8"N 061°06'01.6"W  <i>DFO(6309308-01)</i>
Add	depth of 3.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°21'08.5"N 061°05'50.8"W  <i>DFO(6309308-02)</i>
Delete	depth of 1.8 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067, CA476675	45°21'21.3"N 061°04'20.3"W  <i>DFO(6309308-03)</i>
Add	drying height of 0.1 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA376067, CA476675	45°21'23.3"N 061°04'22.0"W  <i>DFO(6309308-04)</i>
Add	depth of 3.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°21'14.9"N 061°04'21.6"W  <i>DFO(6309308-05)</i>
Add	depth of 3.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°21'07.3"N 061°04'20.2"W  <i>DFO(6309308-06)</i>
Delete	depth of 6.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°20'50.1"N 061°01'56.6"W  <i>DFO(6309308-08)</i>
Add	depth of 2.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°20'53.9"N 061°01'57.9"W  <i>DFO(6309308-09)</i>
Replace	depth of 2.1 metres with depth of 1.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°17'26.2"N 061°02'47.9"W  <i>DFO(6309308-10)</i>
Delete	depth of 0.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067, CA476675	45°16'49.2"N 061°01'32.9"W  <i>DFO(6309308-12)</i>

Add	depth of 0.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276204, CA376067, CA476675	45°16'47.6"N 061°01'37.1"W  <i>DFO(6309308-13)</i>
Add	drying height of 0.5 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA376067	45°14'54.9"N 060°59'45.6"W  <i>DFO(6309308-15)</i>
Add	depth of 3.5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067, CA476675, CA576527	45°19'29.0"N 060°57'17.8"W  <i>DFO(6309308-23)</i>
Add	depth of 0.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067, CA476069	45°12'10.4"N 061°06'56.1"W  <i>DFO(6309309-01)</i>
Add	depth of 4.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°07'32.9"N 061°31'12.5"W  <i>DFO(6309309-06)</i>
<b>4233 - Whitehead Harbour - New Chart - 11-JAN-1991 - NAD 1983</b>		
12-MAR-2021		LNMD. 19-FEB-2021
Add	depth of 0.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067, CA476069	45°12'10.4"N 061°06'56.1"W  <i>DFO(6309309-01)</i>
Add	drying height of 0 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA476069	45°12'41.8"N 061°08'16.9"W  <i>DFO(6309309-02)</i>
Add	drying height of 2.0 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA476069	45°12'41.9"N 061°08'44.0"W  <i>DFO(6309309-03)</i>
Delete	depth of 0.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476069	45°12'32.4"N 061°09'56.8"W  <i>DFO(6309309-04)</i>
Add	drying height of 0.1 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA476069	45°12'33.9"N 061°09'58.0"W  <i>DFO(6309309-05)</i>
Delete	depth of 1.2 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476069	45°12'40.7"N 061°08'15.3"W  <i>DFO(6309309-08)</i>

**4240 - Liverpool Harbour to / à Lockeport Harbour - New Chart - 06-OCT-1989 - NAD 1983**

26-MAR-2021

LNMD. 10-AUG-2018

Amend QG to read Iso G against light 44°01'10.1"N 064°39'44.7"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA376045, CA476202  
(F2021004) LL(408.2) DFO(6309357-01)

**4281 - Canso Harbour and Approaches / et les Approches - New Edition - 27-SEP-2013 - NAD 1983**

12-MAR-2021

LNMD. 19-FEB-2021

Delete depth of 7.3 metres 45°19'02.2"N 060°57'35.7"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-17)

Add depth of 5.8 metres 45°19'02.7"N 060°57'33.4"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-18)

Add depth of 5.2 metres 45°18'57.7"N 060°57'23.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-19)

Replace depth of 4 metres with depth of 2.7 metres 45°19'08.2"N 060°57'35.5"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-20)

Replace depth of 5.8 metres with depth of 4.6 metres 45°18'50.5"N 060°57'27.4"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-21)

Replace depth of 3.3 metres with depth of 3 metres 45°18'42.4"N 060°57'56.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-22)

Add depth of 3.5 metres 45°19'29.0"N 060°57'17.8"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376067, CA476675, CA576527

DFO(6309308-23)

Delete depth of 5.2 metres 45°20'30.1"N 060°59'36.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-24)

Delete depth of 5.5 metres 45°20'23.4"N 060°59'23.9"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-25)

Add depth of 2.7 metres 45°20'30.6"N 060°59'38.4"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA576527

DFO(6309308-26)

Add	depth of 5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'23.4"N 060°59'28.5"W  <i>DFO(6309308-27)</i>
Replace	depth of 3.3 metres with depth of 2.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'24.1"N 060°59'47.6"W  <i>DFO(6309308-28)</i>
Replace	depth of 5.5 metres with depth of 3.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'23.6"N 060°59'38.4"W  <i>DFO(6309308-29)</i>
Replace	depth of 7 metres with depth of 5.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'20.1"N 060°59'42.2"W  <i>DFO(6309308-30)</i>
Replace	depth of 7 metres with depth of 5.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'19.3"N 060°59'41.6"W  <i>DFO(6309308-31)</i>
Add	depth of 4.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'24.3"N 060°59'24.3"W  <i>DFO(6309308-32)</i>
Delete	depth of 6.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'41.4"N 060°59'43.9"W  <i>DFO(6309308-33)</i>
Add	depth of 2.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'43.8"N 060°59'45.6"W  <i>DFO(6309308-34)</i>
Add	depth of 4.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'42.3"N 060°59'44.8"W  <i>DFO(6309308-35)</i>
Add	depth of 3.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'44.4"N 060°59'38.4"W  <i>DFO(6309308-36)</i>
Add	depth of 1.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'37.6"N 060°59'43.7"W  <i>DFO(6309308-37)</i>
Replace	depth of 5.5 metres with depth of 2.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576527	45°20'33.5"N 060°59'41.3"W  <i>DFO(6309308-38)</i>



Replace	depth of 1.5 metres with depth of 0.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476675	45°17'20.8"N 061°02'50.3"W  <i>DFO(6309308-16)</i>
Add	depth of 3.5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067, CA476675, CA576527	45°19'29.0"N 060°57'17.8"W  <i>DFO(6309308-23)</i>
<b>4302 - Canso Lock and Causeway / Écluse et Chaussée Surélevée de Canso - New Chart - 28-SEP-2012 - NAD 1983</b>		
05-MAR-2021		LN/D. 20-NOV-2020
Replace	depth of 3 metres with drying height of 0.9 metres (See Chart No. 1, I10, I15) This notice affects Electronic Navigational Chart: CA576679	45°39'16.3"N 061°25'16.9"W  <i>DFO(6309304-01)</i>
Delete	delete depth of 0.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576679	45°39'13.5"N 061°25'14.4"W  <i>DFO(6309304-02)</i>
Add	drying height of 0.5 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA576679	45°39'13.8"N 061°25'14.8"W  <i>DFO(6309304-03)</i>
Replace	depth of 0.6 metres with drying height of 0.8 metres (See Chart No. 1, I10, I15) This notice affects Electronic Navigational Chart: CA576679	45°39'09.5"N 061°25'07.9"W  <i>DFO(6309304-04)</i>
Add	drying height of 0.1 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA576679	45°38'49.6"N 061°24'38.2"W  <i>DFO(6309304-05)</i>
<b>4321 - Cape Canso to / à Liscomb Island - New Edition - 08-OCT-2004 - NAD 1983</b>		
12-MAR-2021		LN/D. 06-DEC-2019
Add	drying height of 1.2 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA376067	45°21'18.8"N 061°06'01.6"W  <i>DFO(6309308-01)</i>
Delete	depth of 1.8 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067, CA476675	45°21'21.8"N 061°04'21.0"W  <i>DFO(6309308-03)</i>
Add	drying height of 0.1 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA376067, CA476675	45°21'23.3"N 061°04'22.0"W  <i>DFO(6309308-04)</i>
Add	depth of 3.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°21'07.3"N 061°04'20.2"W  <i>DFO(6309308-06)</i>

Delete	depth of 6.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°20'49.7"N 061°01'57.0"W  <i>DFO(6309308-08)</i>
Add	depth of 2.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°20'53.9"N 061°01'57.9"W  <i>DFO(6309308-09)</i>
Replace	depth of 0.9 metres with depth of 0.4 metres (See Chart No. 1, I10)	45°16'47.6"N 061°01'37.1"W  <i>DFO(6309308-14)</i>
Delete	depth of 0.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476069	45°12'32.4"N 061°09'56.4"W  <i>DFO(6309309-04)</i>
Add	drying height of 0.1 metres (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA476069	45°12'33.9"N 061°09'58.0"W  <i>DFO(6309309-05)</i>
Add	depth of 4.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°07'32.9"N 061°31'12.5"W  <i>DFO(6309309-06)</i>
Delete	depth of 7.6 metres (See Chart No. 1, I10)	45°07'34.6"N 061°31'22.2"W  <i>DFO(6309309-07)</i>

**4335 - Strait of Canso and Approaches / et les approches - New Edition - 04-JAN-2008 - NAD 1983**

12-MAR-2021

LNMD. 19-FEB-2021

Add	drying height of 0 fathoms, 4 feet (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA376067	45°21'20.5"N 061°06'01.3"W  <i>DFO(6309308-01)</i>
Delete	depth of 0 fathoms, 5 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067, CA476675	45°21'20.6"N 061°04'17.6"W  <i>DFO(6309308-03)</i>
Add	drying height of 0 feet (See Chart No. 1, I15) This notice affects Electronic Navigational Chart: CA376067, CA476675	45°21'23.3"N 061°04'22.0"W  <i>DFO(6309308-04)</i>
Add	depth of 1 fathom, 5 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376067	45°21'07.3"N 061°04'20.2"W  <i>DFO(6309308-06)</i>

**4379 - Liverpool Harbour - New Edition - 18-JUL-2003 - NAD 1983**

26-MAR-2021

LNMD. 26-FEB-2021

Amend QG to read Iso G against light 44°01'10.0"N 064°39'45.4"W  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA376045, CA476202  
(F2021004) LL(408.2) DFO(6309357-01)

**4395 - LaHave River: Riverport to / à Conquerall Bank - New Edition - 04-JUL-2003 - NAD 1983**

26-MAR-2021

LNMD. 18-DEC-2020

Add anchorage area with legend 'Mooring Buoys / Bouées d'amarrage' joining 44°18'52.2"N 064°24'14.8"W  
(See Chart No. 1, Q44) 44°18'42.5"N 064°24'14.6"W  
44°18'42.3"N 064°24'27.6"W  
44°18'45.5"N 064°24'27.7"W  
44°18'45.3"N 064°24'39.4"W  
44°18'51.6"N 064°24'39.6"W  
44°18'53.0"N 064°24'25.6"W  
and 44°18'52.2"N 064°24'14.8"W  
DFO(6309385-01)

**4406 - Tryon Shoals to / à Cape Egmont - New Edition - 27-FEB-1998 - NAD 1983**

05-MAR-2021

LNMD. 07-AUG-2020

Add depth of 4.9 metres 45°53'49.7"N 063°45'33.9"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376178, CA476183  
DFO(6309332-01)

Delete depth of 2.1 metres 45°53'09.0"N 063°45'00.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376178  
DFO(6309332-02)

Add depth of 1.7 metres 45°53'05.9"N 063°45'07.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376178, CA476183  
DFO(6309332-03)

Delete depth of 1.2 metres 45°53'00.0"N 063°44'30.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376178  
DFO(6309332-04)

Add depth of 0.9 metres 45°52'58.3"N 063°44'32.5"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376178, CA476183  
DFO(6309332-05)

Add depth of 1.3 metres 45°53'27.0"N 063°43'39.3"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376178, CA476183  
DFO(6309332-06)

Add depth of 1.8 metres 45°53'24.0"N 063°43'03.3"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376178, CA476183  
DFO(6309332-07)

Delete depth of 5.8 metres 45°52'40.0"N 063°42'08.0"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA376178  
DFO(6309332-13)



Add	depth of 5.2 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376178, CA476183	45°52'41.9"N 063°42'06.6"W  <i>DFO(6309332-14)</i>
Delete	depth of 1.8 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376178	45°53'06.0"N 063°37'47.0"W  <i>DFO(6309332-23)</i>
Add	depth of 1.5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376178, CA476183	45°53'02.4"N 063°37'48.6"W  <i>DFO(6309332-24)</i>
<b>4416 - Havre de Gaspé - New Edition - 12-JUN-2009 - NAD 1983</b>		
26-MAR-2021		LNMD. 01-FEB-2019
Affix	patch Download Patch - <a href="https://www.notmar.gc.ca/chsftp/patches/4416_6410585_1_202102251540.pdf">https://www.notmar.gc.ca/chsftp/patches/4416_6410585_1_202102251540.pdf</a> This notice affects Electronic Navigational Chart: CA579089	48°52'17.5"N 064°27'56.2"W  <i>DFO(6410585-01)</i>
<b>4426 - Dalhousie Harbour - New Edition - 02-AUG-2002 - NAD 1983</b>		
26-MAR-2021		LNMD. 26-FEB-2021
Amend	Iso G 4s 59ft to read F G against light (See Chart No. 1, P16)	48°04'15.1"N 066°21'59.9"W  <i>(G2020276) LL(1343.8) DFO(6309381-01)</i>
<b>4426 - Rivière Ristigouche / Restigouche River - New Edition - 02-AUG-2002 - NAD 1983</b>		
26-MAR-2021		LNMD. 26-FEB-2021
Amend	Iso G to read F G against light (See Chart No. 1, P16)	48°04'15.4"N 066°22'00.0"W  <i>(G2020276) LL(1343.8) DFO(6309381-01)</i>
<b>4485 - Cap des Rosiers à/to Chandler - New Edition - 17-JUN-2011 - NAD 1983</b>		
26-MAR-2021		LNMD. 13-MAR-2020
Affix	patch Download Patch - <a href="https://www.notmar.gc.ca/chsftp/patches/4485_6410579_1_202102221456.pdf">https://www.notmar.gc.ca/chsftp/patches/4485_6410579_1_202102221456.pdf</a> This notice affects Electronic Navigational Chart: CA379086	48°40'00.0"N 064°20'00.0"W  <i>DFO(6410579-01)</i>
<b>4498 - Pugwash Harbour - New Edition - 26-JUL-2019 - NAD 1983</b>		
05-MAR-2021		
Add	depth of 1.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183, CA576184	45°51'40.5"N 063°40'38.5"W  <i>DFO(6309332-16)</i>
Add	depth of 1.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183, CA576184	45°52'44.3"N 063°40'57.4"W  <i>DFO(6309332-17)</i>
Delete	depth of 3.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576184	45°52'57.2"N 063°40'06.1"W  <i>DFO(6309332-18)</i>

Add	depth of 2.2 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183, CA576184	45°52'57.4"N 063°40'04.8"W  <i>DFO(6309332-19)</i>
Add	depth of 1.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576184	45°52'45.0"N 063°39'48.1"W  <i>DFO(6309332-20)</i>
<b>4498 - Pugwash Harbour and approaches / et les approches - New Edition - 26-JUL-2019 - NAD 1983</b>		
05-MAR-2021		
Add	depth of 4.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376178, CA476183	45°53'49.7"N 063°45'33.9"W  <i>DFO(6309332-01)</i>
Add	depth of 1.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376178, CA476183	45°53'05.9"N 063°45'07.2"W  <i>DFO(6309332-03)</i>
Add	depth of 0.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376178, CA476183	45°52'58.3"N 063°44'32.5"W  <i>DFO(6309332-05)</i>
Add	depth of 1.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376178, CA476183	45°53'27.0"N 063°43'39.3"W  <i>DFO(6309332-06)</i>
Add	depth of 1.8 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376178, CA476183	45°53'24.0"N 063°43'03.3"W  <i>DFO(6309332-07)</i>
Add	depth of 2.9 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183	45°54'15.2"N 063°43'49.4"W  <i>DFO(6309332-08)</i>
Delete	depth of 4.1 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183	45°53'58.7"N 063°42'46.0"W  <i>DFO(6309332-09)</i>
Add	depth of 3.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183	45°53'57.3"N 063°42'46.4"W  <i>DFO(6309332-10)</i>
Replace	depth of 4.4 metres with depth of 4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183	45°54'15.9"N 063°42'20.0"W  <i>DFO(6309332-11)</i>
Add	depth of 2.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183	45°52'33.7"N 063°42'38.4"W  <i>DFO(6309332-12)</i>

Add	depth of 5.2 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376178, CA476183	45°52'41.9"N 063°42'06.6"W  <i>DFO(6309332-14)</i>
Add	depth of 4.7 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183	45°52'33.6"N 063°42'08.1"W  <i>DFO(6309332-15)</i>
Add	depth of 1.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183, CA576184	45°51'40.5"N 063°40'38.5"W  <i>DFO(6309332-16)</i>
Add	depth of 1.3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183, CA576184	45°52'44.3"N 063°40'57.4"W  <i>DFO(6309332-17)</i>
Add	depth of 2.2 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183, CA576184	45°52'57.4"N 063°40'04.8"W  <i>DFO(6309332-19)</i>
Add	depth of 1.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA576184	45°52'45.0"N 063°39'48.1"W  <i>DFO(6309332-20)</i>
Delete	depth of 3 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183	45°52'39.9"N 063°38'41.5"W  <i>DFO(6309332-21)</i>
Add	depth of 2.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476183	45°52'37.6"N 063°38'41.2"W  <i>DFO(6309332-22)</i>
Add	depth of 1.5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376178, CA476183	45°53'02.4"N 063°37'48.6"W  <i>DFO(6309332-24)</i>

**4702 - Corbett Island to / à Ship Harbour Head - New Edition - 28-MAY-2004 - NAD 1983**

26-MAR-2021

LNMD. 23-JUL-2010

Amend	Fl 6s55m6M to read Fl 4s55m4M against light (See Chart No. 1, P16) This notice affects Electronic Navigational Chart: CA276113, CA376429, CA476634 <i>(N2021002) LL(279.8) DFO(6309370-01)</i>	52°50'15.4"N 055°48'24.3"W
-------	---	----------------------------

**4731 - Forteau Bay to / à Domino Run - New Edition - 13-JUN-2003 - Unknown**

26-MAR-2021

LNMD. 11-MAY-2018

Amend	Fl 6s 179ft 6M to read Fl 4s179ft4M against light (See Chart No. 1, P16) This notice affects Electronic Navigational Chart: CA276113, CA376429, CA476634 <i>(N2021002) LL(279.8) DFO(6309370-01)</i>	52°50'12.0"N 055°48'45.4"W
-------	---	----------------------------

**4827 - Hare Bay to / à Fortune Head - New Chart - 13-AUG-2004 - NAD 1983**

19-MAR-2021 LNM/D. 17-JUL-2020

Affix patch 47°27'06.7"N 056°03'52.0"W  
Download Patch - [https://www.notmar.gc.ca/chsftp/patches/4827\\_6309380\\_1\\_202102030731.pdf](https://www.notmar.gc.ca/chsftp/patches/4827_6309380_1_202102030731.pdf)  
This notice affects Electronic Navigational Chart: CA376627  
DFO(6309380-01)

Affix patch 47°28'49.9"N 055°55'01.5"W  
Download Patch - [https://www.notmar.gc.ca/chsftp/patches/4827\\_6309380\\_3\\_202102030729.pdf](https://www.notmar.gc.ca/chsftp/patches/4827_6309380_3_202102030729.pdf)  
This notice affects Electronic Navigational Chart: CA376627  
DFO(6309380-03)

**4830 - Great Bay de l'Eau and Approaches / et les approches - New Edition - 08-NOV-2002 - NAD 1983**

19-MAR-2021 LNM/D. 31-AUG-2018

Affix patch 47°32'55.1"N 055°49'55.3"W  
Download Patch - [https://www.notmar.gc.ca/chsftp/patches/4830\\_6309380\\_2\\_202102030727.pdf](https://www.notmar.gc.ca/chsftp/patches/4830_6309380_2_202102030727.pdf)  
This notice affects Electronic Navigational Chart: CA476323  
DFO(6309380-02)

Affix patch 47°30'37.7"N 055°51'12.1"W  
Download Patch - [https://www.notmar.gc.ca/chsftp/patches/4830\\_6309380\\_4\\_202102030730.pdf](https://www.notmar.gc.ca/chsftp/patches/4830_6309380_4_202102030730.pdf)  
This notice affects Electronic Navigational Chart: CA476323  
DFO(6309380-04)

**4846 - Motion Bay to / à Cape St Francis - New Edition - 15-DEC-1995 - NAD 1983**

05-MAR-2021 LNM/D. 26-JUN-2020

Add subsurface Ocean Data Acquisition System ODAS/SADO with known depth of 100 metres 47°32'33.0"N 052°34'43.2"W  
(See Chart No. 1, L25)  
This notice affects Electronic Navigational Chart: CA376015  
DFO(6309331-01)

**4911 - Entrée à / Entrance to Miramichi River - New Edition - 27-JAN-2006 - NAD 1983**

05-MAR-2021 LNM/D. 30-OCT-2020

Add depth of 4.1 metres 47°08'18.1"N 065°00'07.1"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476133  
DFO(6309333-01)

Delete depth of 7.9 metres 47°08'18.1"N 065°00'04.2"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476133  
DFO(6309333-02)

Add depth of 3.5 metres 47°07'39.2"N 064°59'12.5"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476133  
DFO(6309333-03)

Add depth of 2.5 metres 47°07'27.5"N 064°58'59.3"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476133  
DFO(6309333-04)

Replace depth of 4.5 metres with depth of 4 metres 47°06'27.1"N 064°58'09.5"W  
(See Chart No. 1, I10)  
This notice affects Electronic Navigational Chart: CA476133  
DFO(6309333-05)

Add	depth of 5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476133	47°06'32.7"N 064°57'59.4"W  <i>DFO(6309333-06)</i>
Delete	depth of 5.5 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA476133	47°06'33.1"N 064°57'57.7"W  <i>DFO(6309333-07)</i>
Delete	note: ENSABLEMENT En raison d'ensablement continuels les profondeurs normales et la présentation des isobathes changent constamment. Les navigateurs sont avisés d'être prudents en naviguant dans ces eaux.  SILTING Due to continuous silting, the normal depths and the presentation of the bathymetric contours are constantly changing. Mariners are warned to exercise due caution when navigation in these waters. This notice affects Electronic Navigational Chart: CA476125, CA476133	47°03'46.6"N 064°55'02.3"W  <i>DFO(6309333-08)</i>
Add	note: ENSABLEMENT En raison d'un envasement continuels, les profondeurs et la représentation des contours dans le chenal d'approche de la rivière Miramichi changent constamment. Le chenal ne fait plus l'objet de dragage. On conseille aux navigateurs qui n'ont pas de connaissances locales de ne pas emprunter cette voie.  SILTING Owing to continual silting, the depths and presentation of contours in the approach channel to the Miramichi River are constantly changing and dredging in the area has been discontinued. Mariners should not attempt to enter without local knowledge. This notice affects Electronic Navigational Chart: CA476125, CA476133	47°03'46.7"N 064°55'02.3"W  <i>DFO(6309333-09)</i>
Amend	5.5 mètres (2017) to read 5.4 mètres (2020) against the note ATTENTION and 5.5 metres (2017) to read 5.4 metres (2020) against the note CAUTION This notice affects Electronic Navigational Chart: CA476125, CA476133	47°03'20.6"N 064°55'03.9"W  <i>DFO(6309333-10)</i>
<b>4912 - Miramichi - New Edition - 27-JAN-2006 - NAD 1983</b> 05-MAR-2021		LNMD. 05-JUN-2020
Delete	note: ENSABLEMENT En raison d'ensablement continuels les profondeurs normales et la présentation des isobathes changent constamment. Les navigateurs sont avisés d'être prudents en naviguant dans ces eaux.  SILTING Due to continuous silting, the normal depths and the presentation of the bathymetric contours are constantly changing. Mariners are warned to exercise due caution when navigation in these waters. This notice affects Electronic Navigational Chart: CA476125, CA476133	47°11'18.0"N 065°10'41.6"W  <i>DFO(6309333-08)</i>



Delete	depth of 9 metres 0 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA579046	47°22'46.0"N 061°51'10.0"W  <i>DFO(6410560-07)</i>
Add	depth of 8 metres 4 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA579046	47°22'46.0"N 061°51'10.0"W  <i>DFO(6410560-08)</i>
Delete	depth of 4 metres 3 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA579046	47°22'32.6"N 061°51'17.3"W  <i>DFO(6410560-09)</i>
Add	depth of 4 metres 0 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA579046	47°22'33.0"N 061°51'17.3"W  <i>DFO(6410560-10)</i>
Add	depth of 5 metres 9 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA579046	47°22'23.3"N 061°51'01.7"W  <i>DFO(6410560-12)</i>
Delete	depth of 4 metres 4 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA579046	47°22'49.7"N 061°51'20.1"W  <i>DFO(6410560-13)</i>
Add	depth of 4 metres 1 decimetre (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA579046	47°22'49.7"N 061°51'20.1"W  <i>DFO(6410560-14)</i>
Delete	depth of 6 metres 8 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA579046	47°22'39.1"N 061°51'14.3"W  <i>DFO(6410560-15)</i>
Add	depth of 6 metres 3 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA579046	47°22'39.1"N 061°51'14.4"W  <i>DFO(6410560-16)</i>
Add	depth of 5 metres 7 decimetres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA579046	47°22'43.8"N 061°51'16.1"W  <i>DFO(6410560-17)</i>
<b>5032 - Approaches to / Approches à White Bear Arm - New Chart - 31-JAN-2003 - NAD 1983</b>		
26-MAR-2021		LNMD. 26-FEB-2021
Amend	Fl 6s55m6M to read Fl 4s55m4M against light (See Chart No. 1, P16) This notice affects Electronic Navigational Chart: CA276113, CA376429, CA476634 <i>(N2021002) LL(279.8) DFO(6309370-01)</i>	52°50'15.5"N 055°48'24.5"W

**8014 - Grand Bank / Grand Banc: Northeast Portion / Partie nord-est - New Edition - 25-JUL-2003 - NAD 1983**

19-MAR-2021

LNMD. 15-MAR-2019

Add private yellow ODAS/SADO lighted pillar buoy Fl(5) Y 20s, Priv  
(See Chart No. 1, Q58)  
This notice affects Electronic Navigational Chart: CA276101

47°14'12.0"N 050°57'00.0"W

*DFO(6309327-01)*

**8048 - Cape Harrison to / à St. Michael Bay - New Edition - 20-JUN-2003 - NAD 1983**

26-MAR-2021

LNMD. 02-OCT-2020

Amend Fl 6s 179ft 6M to read Fl 4s179ft4M against light  
(See Chart No. 1, P16)  
This notice affects Electronic Navigational Chart: CA276113, CA376429, CA476634

52°50'24.0"N 055°48'26.0"W

*(N2021002) LL(279.8) DFO(6309370-01)*



## Section 3: Radio Aids to Marine Navigation Corrections

### \*321/21 Radio Aids to Marine Navigation 2021 (Atlantic, St. Lawrence, Great Lakes, Lake Winnipeg, Arctic and Pacific)

#### Page 2-2

#### ADD AS FOLLOWS:

Table 2-1 - Halifax MCTS/VCS - Ship/Shore Communications

Sites located at	Channels	Frequencies		Remarks
		Transmit	Receive	
...	...	...	...	...
Lockeport, N.S. 43°39'49"N 065°07'47"W	Ch16 Ch21B Ch24 Ch26 Ch70	-	-	VHF Direction Finding service is available. Ch24, Ch26, 2142 and 2206: Facilities are available for connecting ships directly to the commercial telephone system on shore.
	-	-	2182 2142 2206	
...	...	...	...	...

#### Pages 2-18 to 2-20

#### ADD AS FOLLOWS:

Table 2-8 - Les Escoumins MCTS/VCF - Broadcasts

Time UTC	Site	Frequency or Channel	Contents
...	...	...	...
04:37	Natashquan La Vernière	2598J3E 2749J3E	Radiotelephony (French followed by English) ...
...	...	...	...
08:47	Natashquan La Vernière	2598J3E 2749J3E	Radiotelephony (French followed by English) ...
09:37	Natashquan La Vernière	2598J3E 2749J3E	Radiotelephony (French followed by English) ...
...	...	...	...
14:07	Natashquan La Vernière	2598J3E 2749J3E	Radiotelephony (French followed by English) ...
...	...	...	...
17:37	Natashquan La Vernière	2598J3E 2749J3E	Radiotelephony (French followed by English) ...
...	...	...	...

Time UTC	Site	Frequency or Channel	Contents
23:17	Natashquan La Vernière	2598J3E 2749J3E	Radiotelephony (French followed by English) ...
Continuous	Forillon Carleton Natashquan Cap-aux-Meules	Ch21B	Radiotelephony (French followed by English) ...
	Pointe Heath Harrington Harbour	Ch25B	
	Newport Havre St-Pierre La Romaine	Ch83B	
Continuous	Lac Daigle Grosses-Roches Cap à l'Est	Ch21B	Radiotelephony (French followed by English) ...
	Mont-Louis Mont-Joli Sacré-Cœur	Ch83B	

**Pages 2-47 to 2-48**

**ADD AS FOLLOWS:**

**Table 2-24 - Sydney MCTS/VCO - Broadcasts**

Time UTC	Site	Frequency or Channel	Contents
00:40	Port Caledonia	2749J3E	Radiotelephony (English followed by French) ...
...	...	...	...
07:40	Port Caledonia	2749J3E	Radiotelephony (English followed by French) ...
...	...	...	...
14:40	Port Caledonia	2749J3E	Radiotelephony (English followed by French) ...
...	...	...	...
20:10	Port Caledonia	2749J3E	Radiotelephony (English followed by French) ...
...	...	...	...
Continuous	Port Caledonia Point Escuminac Montague Fox Island	Ch21B	Radiotelephony (English followed by French) ...
	Cape North Cape Egmont	Ch83B	

**Page 5-15**

**AMEND AS FOLLOWS FOR SECTION 5.8:**

Officer / Officier :		Return to / Envoyer à : <b>Tom King Daniel Huang / Brent Tompkins</b>
Ship / Navire :		Marine & Transport Weather Services / Services météorologiques marine et transport
Position Latitude:		National Service Operations / Services opérationnels nationaux Meteorological Service of Canada / Service météorologique du Canada
Position Longitude:		Environment and Climate Change Canada / Environnement et Changement climatique Canada
Date:		P.O. Box / Case Postale 370 Gander, NL A1V 1W7
		Fax / Télécopieur : 709-256-6627
		Email / Courriel : <a href="mailto:Tom.King@canada.ca">Tom.King@canada.ca</a> <a href="mailto:Daniel.Huang@canada.ca">Daniel.Huang@canada.ca</a> / <a href="mailto:Brent.Tompkins@canada.ca">Brent.Tompkins@canada.ca</a>

**Page 5-28**

**AMEND AS FOLLOWS FOR SECTION 5.9.7:**

Internet link to the FBDN651 EKMI warnings for Greenlandic waters within METAREA XVIII:  
[http://dd.weather.gc.ca/cgi-bin/bulletin\\_search.pl?product=FB&issuer=EKMI&location=DN51](http://dd.weather.gc.ca/cgi-bin/bulletin_search.pl?product=FB&issuer=EKMI&location=DN51)

## Section 4: Sailing Directions and Small Craft Guide Corrections

---

ATL 101 — Newfoundland, Northeast and East Coasts, Second Edition, 2013 —

Chapter 1 — Paragraph 59.1

Delete: 0830 to 1630

Replace by: 0800 to 1600

(N2021-00.1)

Chapter 4 — Paragraph 260, after “SW tip of Black Island.”

Insert: The previously mentioned shoal is marked by starboard hand light **buoy** DHL2 (360.54).

(N2021-00.2)

ATL 102 — Newfoundland, East and South Coasts, Second Edition, 2008 —

Chapter 2 — Paragraph 120, after “0.3 m (1 ft)”

Insert: and marked by an isolated danger **buoy** (488.5)

(N2021-00.3)

ATL 108 — Gulf of St. Lawrence (Southwest Portion), First Edition, 2006 —

Chapter 4 — Paragraph 207

Delete: (2010) between 3 and 6 feet (0.9 and 1.7 m)

Replace by: (2020) between 1 and 7 feet (0.3 and 2 m)

(Q2020-054.1)

Chapter 4 — Paragraph 207

Delete: There is also a **launching ramp**.

(Q2020-054.2)

Chapter 4 — Delete paragraph 250

Replace by: 250 The Carleton-sur-Mer **public wharf** is administered by *Fisheries and Oceans Canada* in partnership with the *Town of Carleton-sur-Mer*. The inside depths of the harbour are between 0.4 m on the N side and 5.2 m on the SE side (2019). There is a crib with a depth of 4 m in the middle of the harbour. There are floating docks there. The harbour is protected at the SE by a **breakwater** and at the SW by another **breakwater** attached to the wharf. A **light** stands on the end of this breakwater. This light operates at night only. These facilities are managed by the *Harbour Authority of Carleton-sur-Mer*.

(Q2021-004.1)

Chapter 4 — In the vicinity of paragraph 250

Replace the **CARLETON (2000)** photograph and replace it with the new **CARLETON-SUR-MER (2020)** photograph provided in **Section 4** of this Monthly Edition.

<https://www.notmar.gc.ca/publications/monthly-mensuel/images/ed0321-sec4-atl108-carleton-sur-mer-2020.jpg>

(Q2021-004.2)

ATL 109 — Gulf of St. Lawrence (Northeast Portion), First Edition, 2006 —

Chapter 4 — Paragraph 76, after “bold mountain face.”

Insert: Port hand light **buoy** XLH1 (*196.1*) is moored off the NE shore close within the harbour entrance.

(N2021-00.4)

ATL 110 — St. Lawrence River — Cap Whittle/Cap Gaspé to Les Escoumins and Anticosti Island, Third Edition, 2011 —

Chapter 1 — Paragraph 132

Delete: 3234

Replace by: 3395

(Q2021-002.1)

Chapter 1 — Paragraph 139

Delete: 22 m

Replace by: 41 m

(Q2021-002.2)

Chapter 1 — Paragraph 142

Delete: 42 m

Replace by: 60 m

(Q2021-002.3)

Chapter 1 — Paragraph 146

Delete: 36 m

Replace by: 46 m

(Q2021-002.4)

Chapter 1 — Paragraph 153, after “there is a ramp at the wharf.”

Add: A floating dock, approximately 10 metres long, is located west of the launching ramp.

(Q2021-002.5)

Chapter 1 — In the vicinity of paragraph 154, in **Table 1.2 Havre-Saint-Pierre Wharves**

Delete: 9.2

Replace by: 9.1

(Q2021-002.6)

Chapter 1 — In the vicinity of paragraph 154, in **Table 1.2 Havre-Saint-Pierre Wharves**

Delete: 10.2

Replace by: 10.1

(Q2021-002.7)

Chapter 1 — Paragraph 158

Delete: 29 m

Replace by: 44 m

(Q2021-002.8)

ATL 111 — St. Lawrence River — Île Verte to Québec and Fjord du Saguenay, Third Edition, 2007 —

Chapter 2 — After paragraph 32

Insert: 32.1 There is a spoil ground approximately 0.4 mile NE of the Saint-Michel-de-Bellechasse marina.

(Q2021-003)

Chapter 3 — Paragraph 38

Delete: 9.1 m

Replace by: 9.0 m

(Q2021-008.1)

Chapter 3 — Paragraph 136

Delete: The approach to the small craft basin is restricted by a **shoal** with a depth of 0.3 m (2015).

(Q2021-001.1)

Chapter 3 — In the vicinity of paragraph 136

Replace the **BERTHIER-SUR-MER** diagram with the new one provided in **Section 4** of this Monthly Edition.

<https://www.notmar.gc.ca/publications/monthly-mensuel/images/ed0321-sec4-atl111-berthier-sur-mer-20210120.pdf>

(Q2021-001.2)

ATL 112 — St. Lawrence River — Cap-Rouge to Montréal and Rivière Richelieu, Third Edition, 2009 —

Chapter 1 — Paragraph 56

Delete: 1.5 m

Replace by: 1.1 m

(Q2021-005.1)

Chapter 2 — In the vicinity of paragraph 138, **Table 2.3 Contrecoeur Terminal Wharves**

Delete: 5.8 m

Replace by: 5.7 m

(Q2021-007.1)

ATL 120 — Labrador, Camp Islands to Hamilton Inlet (including Lake Melville), Second Edition, 2020 —

Chapter 4 — Paragraph 220 - after “1 mile NNE,”

Insert: or the channel lying between Black Rocks and George Island

(N2021-00.5)

Chapter 5 — Paragraph 25, after last line

Add: North cardinal light **buoy** HG (287.4) marks the NE shoal having a least depth of 32 feet (9.8 m) extending into the previously mentioned channel NE of Black Rocks which is used by the local ferry.

(N2021-00.6)

Chapter 6 — Before paragraph 1

Delete: 4725, 5143, 4728, 4722, 5163, 5162

Replace by: 4722, 5162, 5163, 5164, 5165

(N2021-00.7)

Chapter 6 — Before paragraph 5

Delete: *Charts 5163, 4725*

Replace by: *Chart 5163*

(N2021-00.8)

Chapter 6 — Before paragraph 6

Delete: 4725

Replace by: 5164

(N2021-00.9)

Chapter 6 — Before paragraph 10 Delete: 4725 Replace by: 5164	(N2021-01.0)
Chapter 6 — Before paragraph 14 Delete: 4725 Replace by: 5164	(N2021-01.1)
Chapter 6 — Paragraph 18 Delete: of unknown depth and dangerous to surface navigation Replace by: with a least depth of 1.5 m (6 ft)	(N2021-01.2)
Chapter 6 — Before paragraph 26 Delete: 5143 Replace by: 5164	(N2021-01.3)
Chapter 6 — Paragraph 29 Delete: 1.5 m (5 ft) Replace by: 1.2 m (4 ft)	(N2021-01.4)
Chapter 6 — Paragraph 31 Delete: 4 m (13 ft) Replace by: 3.6 m (12 ft)	(N2021-01.5)
Chapter 6 — Paragraph 31 Delete: 3 m (10 ft) Replace by: 2.7 m (9 ft)	(N2021-01.6)
Chapter 6 — Paragraph 50 Delete: 4.9 m Replace by: 4.8 m	(N2021-01.7)
Chapter 6 — Before paragraph 51 Delete: 4728, 5143 Replace by: 5165, 5164	(N2021-01.8)
Chapter 6 — Paragraph 51 Delete: 24 feet (7.3 m) Replace by: 25 feet (7.6 m)	(N2021-01.9)
Chapter 6 — Paragraph 51 Delete: 29-foot (8.8-m) Replace by: 30-foot (9.1-m)	(N2021-02.0)

Chapter 6 — Paragraph 52  
Delete: 9 feet (2.7 m)  
Replace by: 10 feet (2.9 m)

(N2021-02.1)

Chapter 6 — Paragraph 60  
Delete: 3 feet (0.9 m)  
Replace by: 2 feet (0.6 m)

(N2021-02.2)

Chapter 6 — Before paragraph 71  
Delete: 4728  
Replace by: 5165

(N2021-02.3)

Chapter 6 — Paragraph 78  
Delete: “200 feet (61 m) ... 28 feet (8.5 m)”  
Replace by: 328 feet (100 m) and a least charted depth of 31 feet  
(9.5 m) in 2018

(N2021-02.4)

CEN 301 — St. Lawrence River, Montréal to Kingston, Second Edition, 2010 —

Chapter 2 — After paragraph 5  
Insert: 5.1 *Lower Beauharnois Lock* **light** is shown from the outer  
end of the NW approach wall.

(C2021-001.01)

Chapter 2 — Adjacent to paragraph 5.1, add a light pictograph.

(C2021-001.02)



## Section 5: List of Lights, Buoys and Fog Signals Corrections

The amendments are highlighted and deletions are crossed out. For general and region-specific information on the List of Lights, click on the following links: [Newfoundland and Labrador Coast](#), [Atlantic Coast](#), [Inland Waters](#) and [Pacific Coast](#).

No.	Name	Position ----- Latitude N. Longitude W.	Light Characteristics	Focal Height in m. above water	Nomi- nal Range	Description ----- Height in meters above ground	Remarks ----- Fog Signals
-----	------	--	--------------------------	--	-----------------------	--	---------------------------------

### NEWFOUNDLAND AND LABRADOR COAST

#### NEWFOUNDLAND AND LABRADOR COAST (LL 269.99 – 325.23)

279.3 <del>H0086.7</del>	Twin Islands Light	N. of Ship Harbour Head. 52 40 18.0 055 44 50.0	FI W 4s	30.8	5	Cylindrical Mast, red and white cylindrical daymark. 3.0	Flash 1 s; eclipse 3 s. Seasonal.  Chart:4701 Edn 03/21 (N21-006)
279.31 <del>H0086.65</del>	Pigeon Island Light	St. Michaels Bay. 52 43 01.7 055 51 25.1	FI G 4s	11.5	4	Square skeleton tower, green and white rectangular daymark. 5.9	Flash 1 s; eclipse 3 s. Seasonal.  Chart:5032 Edn 03/21 (N21-003)
279.4 <del>H0086.4</del>	Deepwater Island Light	St. Michaels Bay. 52 43 34.0 055 53 50.9	FI W 4s	7.6	6	Square skeleton tower, red and white rectangular daymark. 4.6	Flash 1 s; eclipse 3 s. Visible 180°. Seasonal.  Chart:5032 Edn 03/21 (N21-004)
279.7 <del>H0086.6</del>	Goose Island Light	Charlottetown Harbour entrance. 52 47 36.0 056 06 09.0	FI W 4s	7.6	6	Square skeleton tower, red and white rectangular daymark. 4.3	Flash 1 s; eclipse 3 s. Seasonal.  Chart:5032 Edn 03/21 (N21-007)
279.74 <del>H0086.5</del>	Bar Tickle Light	52 46 45.0 055 54 20.0	FI R 4s	15.3	4	Square skeleton tower, red and white rectangular daymark. 4.5	Flash 1 s; eclipse 3 s. Seasonal.  Chart:5032 Edn 03/21 (N21-005)
279.8 <del>H0086.2</del>	Cape Bluff Light	N. of St. Michaels Bay. 52 50 13.2 055 48 24.0	FI W 4s	54.7	4	Red Mast, red and white rectangular daymark, white horizontal band. 3.0	Flash 1 s; eclipse 3 s. Seasonal.  Chart:5032 Edn 03/21 (N21-002)
297.5	Epinette Point light buoy H7	Lake Melville, W. of point. 53 31 20.6 059 56 56.4	FI G 4s	.....	.....	Green spar, marked "H7".	Seasonal (in place year round).  Chart:5165 Edn 03/21 (N21-039)

#### BONAVISTA BAY (LL 396 – 449.5)

439.4 <del>H0544.5</del>	Happy Adventure East Wharf Light	48 38 04.9 053 45 19.3	FI R 4s	.....	2	Mast. 2.6	Year round.  Chart:4855 Edn 03/21 (N21-001)
-----------------------------	----------------------------------	---------------------------	---------	-------	---	--------------	--

Notices to Mariners – Monthly Eastern Edition  
Section 5: List of Lights, Buoys and Fog Signals Corrections

No.	Name	Position ----- Latitude N. Longitude W.	Light Characteristics	Focal Height in m. above water	Nomi- nal Range	Description ----- Height in meters above ground	Remarks ----- Fog Signals
-----	------	--	--------------------------	--	-----------------------	--	---------------------------------

ATLANTIC COAST

**BAY OF FUNDY, N.S. (LL 163 – 268)**

191 H3956	Minas Basin	On outer SW. corner of wharf at Delhaven. 45 12 07.6 064 22 48.5	F R .....	7.3	5	Pipe swing pole, red and white and red triangular daymark. 5.2	Radar reflector. Year round.  Chart:4140 Edn 03/21 (F21-013)
228 H3880	Westport	On outer end of public wharf and breakwater. 44 15 53.2 066 20 51.9	Fl G 4s	5.0	6	Pipe swing pole. 3.3	Flash 1 s; eclipse 3 s. Operates at night only. Year round.  Chart:4118 Edn 03/21 (F20-051, F21-001)
228.5 H3875	Freeport South Breakwater	On breakwater. 44 16 00.4 066 19 44.5	Fl W 4s	4.2	6	Pipe swing pole. 3.3	Flash 1 s; eclipse 3 s. Operates at night only. Year round.  Chart:4118 Edn 03/21 (F20-052, F21-002)
230.2 H3864.5	East Sandy Cove	On outer end of wharf. 44 29 10.8 066 05 04.3	Fl R 4s	4.3	5	Pipe swing pole, red and white triangular daymark, red triangle in centre. 3.7	Flash 1 s; eclipse 3 s. Operates at night only. Year round.  Chart:4118 Edn 03/21 (F20-054)
238 H3852	Meteghan River	At inner end of breakwater. 44 13 11.8 066 08 37.2	Fl W 4s	7.5	6	Pipe swing pole. 5.6	Operates at night only. Year round.  Chart:4118 Edn 03/21 (F21-006)

**NOVA SCOTIA, SOUTHEAST COAST (LL 327 – 684.02)**

408.2 H3736	Moose Point	Outer end of breakwater. 44 01 10.2 064 39 45.5	iso G 2s	.....	5	Cylindrical mast. 3.7	Radar reflector. Operates at night only. Year round.  Chart:4379 Edn 03/21 (F21-004)
422	False LaHave light and bell buoy T51	E. of Cape LaHave Island. 44 12 36.3 064 19 03.7	Fl G 4s	.....	.....	Green, marked "T51".	Year round.  Chart:4384 Edn 03/21 (F21-014)
463 H3676	Big Tancook Island NW Cove	On outer end of wharf, Northwest Cove. 44 27 52.3 064 10 17.9	Fl G 4s	.....	4	Pipe swing pole, green- white-black square daymark. 2.4	Flash 1 s; eclipse 3 s. Operates at night only. Year round.  Chart:4381 Edn 03/21 (F20-055)
655	Flying Point Shoals light and whistle buoy TA4	W. of shoals. 45 11 59.5 061 13 09.3	Fl R 4s	.....	.....	Red, marked "TA4".	Year round.  Chart:4233 Edn 03/21 (G21-004)
658	Southwest Bull light and bell buoy PU1	SE. of rock. 45 11 09.1 061 08 20.3	Fl G 4s	.....	.....	Green, marked "PU1".	(Winter spar.) Year round.  Chart:4233 Edn 03/21 (G21-001)

Notices to Mariners – Monthly Eastern Edition  
Section 5: List of Lights, Buoys and Fog Signals Corrections

No.	Name	Position ----- Latitude N. Longitude W.	Light Characteristics	Focal Height in m. above water	Nomi- nal Range	Description ----- Height in meters above ground	Remarks ----- Fog Signals
666.8	Andrew Island East Cardinal light and whistle buoy PK	<b>E. of island.</b> 45 17 36.0 060 52 58.0	Q(3) W 10s	.....	.....	Black, yellow and black, marked "PK".	Year round.  Chart:4281 <b>Edn 03/21 (G21-009)</b>
670	Man of War Rock light and bell buoy PK7	E. of rock. 45 19 41.4 060 56 56.4	Fl G 4s	.....	.....	Green, marked "PK7".	Year round.  Chart:4281 <b>Edn 03/21 (G21-002)</b>
<b>CAPE BRETON ISLAND, N.S. (LL 704.85 – 882.5)</b>							
791.5	Little Bras d'Or Entrance light buoy U9	<b>At the entrance to the harbour.</b> 46 18 46.2 060 17 05.2	Fl G 4s	.....	.....	Green, marked "U9".	Seasonal.  Chart:4276 <b>Edn 03/21 (G21-005)</b>
<b>GULF OF ST. LAWRENCE (LL 883.2 – 940.3, 1169.1 – 1426, 1477.5 – 1584)</b>							
1310 H1580	<b>Caraquet range</b>	NE. of Stoke Point. 47 48 30.0 064 50 27.8	F Y	.....	8.1	13 White square tower with red vertical stripe. 8.2	Operates 24 h. Seasonal.
1311 H1580.1		226°47' 1091.4 m from front.	F <b>G</b>	.....	.....	<b>18</b> Square skeleton tower, white daymark with red vertical stripe. 11.3	Operates 24 h. Seasonal.  Chart:4913 <b>Edn 03/21 (G20-273)</b>
1313.2 H1581.5	<b>Middle Caraquet range</b>	47 48 09.7 064 53 09.0	F R	.....	.....	<b>16</b> Square skeleton tower, red daymark with white vertical stripe. 5.4	Operates 24 h. Seasonal.
1313.3 H1581.51		244°07' 355.0 m from front.	F R	.....	.....	<b>17</b> Square skeleton tower, red daymark with white vertical stripe. 14.2	Operates 24 h. Seasonal.  Chart:4913 <b>Edn 03/21 (G20-269, 272)</b>
1314.2 H1581.7	<b>Stoke Point range</b>	47 48 21.4 064 51 34.2	F R	.....	.....	14 Square skeleton tower, red daymark with white vertical stripe. 3.6	Visible in line of range. Operates 24 h. Seasonal.
1314.3 H1581.71		093°46' 124.2 m from front.	F R	.....	.....	14 Square skeleton tower, red daymark with white vertical stripe. 8.2	Visible in line of range. Operates 24 h. Seasonal.  Chart:4920 <b>Edn 03/21 (G20-266, 267)</b>
1343.6 H1618	Dalhousie Wharf	Outer end of wharf. 48 04 17.8 066 21 37.0	Fl G 4s	.....	<b>5</b>	Square skeleton tower, <b>green-white-black square</b> daymark. 6.8	Flash 1 s; eclipse 3 s. <del>Operates at night only.</del> Year round.  Chart:4426 <b>Edn 03/21 (G20-275)</b>

Notices to Mariners – Monthly Eastern Edition  
Section 5: List of Lights, Buoys and Fog Signals Corrections

No.	Name	Position ----- Latitude N. Longitude W.	Light Characteristics	Focal Height in m. above water	Nomi- nal Range	Description ----- Height in meters above ground	Remarks ----- Fog Signals
1343.7 H1619	<b>Dalhousie Harbour East range</b>	48 04 15.2 066 21 57.3	Iso G 1s	14.5	16	Square skeleton tower, white daymark, red vertical stripe. 12.7	Visible in line of range. Year round.
1343.8 H1619.1		268°10' 49.4 m from front.	F G .....	.....	14	Square skeleton tower, white daymark with red vertical stripe. 15.8	Visible in line of range. Operates 24 h. Year round.
1409 H1727	Percé	On <del>outer</del> end of wharf. 48 31 15.1 064 12 37.7	Fl R 6s	9.8	6	Skeleton tower. 6.5	Flash 1 s; eclipse 5 s. Operates at night only. Omnidirectional. Seasonal.
Chart:4426 Edn 03/21 (G20-276)							
Chart:4485 Edn 03/21 (Q20-219)							

**PRINCE EDWARD ISLAND (LL 942 – 1084.7)**

1049.4	Grand Tracadie light buoy JH16	Tracadie Bay. 46 24 19.2 062 59 59.0	Q R 1s	.....	.....	Red spar, marked "JH16".	Buoy may be repositioned due to shifting channel. Seasonal.
Chart:N/A Edn 03/21 (G20-271)							

**ST. LAWRENCE RIVER (LL 1584.5 – 1772, 1823.8 – 2185.7, 2273 – 2365.95)**

1663.7 H1994.6	Sept-Îles, Iron Ore range No. 2	On an hangar at dock no. 2. 50 11 20.3 066 22 14.8	Iso Y 4s	10.0	.....	Mast, orange daymark with black vertical stripe.	Private aid. Privately maintained by Iron Ore Company of Canada. Visible in line of range. Operates 24 h. Year round.
1663.71 H1994.61		N. of Pointe aux Basques. 122°44' 495.8 m from front.	Iso Y 4s	23.7	.....	Mast, orange diamond daymark with black vertical stripe.	Private aid. Privately maintained by Iron Ore Company of Canada. Visible in line of range. Operates 24 h. Year round.
1682.4	Petite-Tourelle	At the end of breakwater. 49 10 11.7 066 22 19.6	Iso R 2s	.....	3	Cylindrical mast. 7.6	Private aid. Seasonal.
Chart:1220 Edn 03/21 (Q21-014, 015)							
Chart:4026 Edn 03/21 (Q20-226)							

**INLAND WATERS**

**ST. LAWRENCE RIVER SEAWAY (LL 0.05 - 401, 1193 – 1204.5)**

32.1	Beauharnois lower lock	On point of N. pier. 45 19 26.6 073 54 58.7	F R .....	6.0	5	.....	Seasonal (in place year round).
Chart:1430 Edn 03/21 (Q20-217)							

Notices to Mariners – Monthly Eastern Edition  
Section 5: List of Lights, Buoys and Fog Signals Corrections

No.	Name	Position ----- Latitude N. Longitude W.	Light Characteristics	Focal Height in m. above water	Nomi- nal Range	Description ----- Height in meters above ground	Remarks ----- Fog Signals
111 H2548	Pointe Dupuis range	On île <b>Marchand</b> . 45 07 39.8 074 24 34.1	F <b>G</b> .....	9.0	14	White square skeleton tower, orange triangular daymark <b>with</b> black vertical stripe. 8.4	<b>Operates 24 h.</b> Seasonal.
112 H2548.1		086°30' 400.8 m from front.	F G .....	20.0	14	White skeleton tower, orange triangular daymark with black vertical stripe. 19.5	Operates 24 h. Seasonal.  <b>Chart:1432</b> <b>Edn 03/21 (B21-009)</b>

**DETROIT RIVER (LL 624 – 707.5)**

667	Fort Malden range	E. side of river. 42 06 51.0 083 06 42.9	F R .....	<b>15.1</b>	<b>15</b>	<b>Square</b> skeleton tower, orange <b>triangular</b> daymark <b>with</b> black vertical stripe. 8.0	Visible in line of range. <b>Operates 24 h.</b> Year round.
668		162°30' 116.7 m from front.	F R .....	<b>24.5</b>	<b>15</b>	<b>Square</b> skeleton tower, orange <b>triangular</b> daymark <b>with</b> black vertical stripe. 16.9	Visible in line of range. <b>Operates 24 h.</b> Year round.  <b>Chart:14853 (U.S.)</b> <b>Edn 03/21 (B21-004, 005)</b>

## Marine Information Report and Suggestion Sheet

Name of Ship or Sender: ..... Date: .....

Address of Sender: .....

Street # Street Name

Town / City: ..... Prov / State: ..... Postal Code / Zip Code: .....

Tel / Fax / E-mail address of sender: .....

Observation Date: ..... Time (UTC): .....

Geographical Position: .....

Coordinate Position: Lat: ..... Long: .....

Position Method:  DGPS  GPS with WAAS  GPS  Radar  Other

Horizontal Datum Used:  WGS84  NAD27  Other

Estimated Position Accuracy: .....

Chart #: ..... Horizontal Datum:  NAD83  NAD27

Chart Edition: ..... Last Correction applied: .....

Publications affected (Quote the edition and page number): .....

\*Full details (Attach additional sheets as necessary): .....

Mariners are requested to notify the responsible authorities when new or suspected dangers to navigation are discovered, changes are observed in aids to navigation, or corrections to publications are seen to be necessary.

*In the case of new or suspected dangers to navigation, it is important that all details be given in order to aid with future investigations. Items of interest include heights, depths, physical description, type of bottom and equipment method used to position the item. It is helpful to mark details on the chart, which will be promptly replaced by the Canadian Hydrographic Service.*

Reports should be made to the nearest Marine Communications and Traffic Services centre (MCTS) and should be confirmed in writing to:

Leader, Notices to Mariners  
Canadian Coast Guard  
Department of Fisheries and Oceans  
Montreal, QC H2Y 2E7  
[Notmar.XNCR@dfo-mpo.gc.ca](mailto:Notmar.XNCR@dfo-mpo.gc.ca)

In the case of information concerning aids to navigation or the *List of Lights, Buoys and Fog Signals* publication.

**OR**

Director General, Canadian Hydrographic Service &  
Oceanographic Services  
Department of Fisheries and Oceans  
Ottawa, ON K1A 0E6  
[CHSinfo@dfo-mpo.gc.ca](mailto:CHSinfo@dfo-mpo.gc.ca)

In the case of new or suspected dangers to navigation or where corrections to *Sailing Directions* appear to be necessary.

For general questions on Canadian Coast Guard programs or services, please send an e-mail to:  
[info@dfo-mpo.gc.ca](mailto:info@dfo-mpo.gc.ca)