



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Notices to Mariners

Edition No. 04-2023
April 28, 2023



Safety First, Service Always

Monthly Summary of Temporary and Preliminary Notices

Canada 

Notices to Mariners – Monthly Summary of Temporary and Preliminary Notices
Edition No. 04-2023

Aussi disponible en français :
Avis aux navigateurs – Sommaire mensuel des avis temporaires et préliminaires
Édition n° 04-2023

Published under the Authority of:

Canadian Coast Guard Programs
Aids to Navigation and Waterways
Fisheries and Oceans Canada
Montreal, QC H2Y 2E7

For more information, contact Notmar.XNCR@dfo-mpo.gc.ca.

© His Majesty the King in Right of Canada,
as represented by the Minister of Fisheries, Oceans
and the Canadian Coast Guard, 2023.

Cat. No. Fs151-19E-PDF (Electronic PDF, English)
ISSN 2561-5106

Cat. No. Fs151-19F-PDF (Electronic PDF, French)
ISSN 2561-5114

A web version is available here:

<https://www.notmar.gc.ca/temp-pre-monthly> (English)

<https://www.notmar.gc.ca/temp-pre-mensuel> (French)

Explanatory Notes

Geographical positions refer directly to the graduations of the largest scale Canadian Hydrographic Service chart (unless otherwise indicated).

Bearings refer to the true compass and are measured clockwise from 000° (North) clockwise to 359°; those relating to lights are from seaward.

Visibility of lights is that in clear weather.

Depths - The units used for soundings (metres, fathoms or feet) are stated in the title of each chart.

Elevations are normally given above Higher High Water, Large Tide (unless otherwise indicated).

Explanation of Temporary and Preliminary Notices to Mariners

Certain Notices to Mariners appearing in the monthly editions have a (T) or (P) appended to the regular number. These letters indicate that the information contained in the notice is of a temporary or preliminary nature, respectively.

Temporary (T) Notices

If a temporary change in conditions affecting navigation exists and if the change will be effective for a period of over three months, a temporary (T) notice will be published. Temporary changes which are effective for periods of less than three months will not normally be published (unless it is of exceptional interest). Otherwise, information will be promulgated as a Navigational Warning (NAVWARN) by the Canadian Coast Guard Marine Communications and Traffic Services (MCTS) Centre(s) in the affected area. (T) notices will be cancelled as necessary.

Please note that (T) notices with an end date will be automatically cancelled once the end date has passed. In the event of a change to these notices, a new Notice to Mariners will be issued.

Preliminary (P) Notices

- a. When important changes affecting navigation are to take place in the near future, a Notice to Mariners describing the change will be published, so that mariners will have advance information on the change. Such notices will be designated (P).
- b. When a change in conditions affecting navigation has taken place but full information is not available, a preliminary (P) notice giving available information will be published. This notice will be followed by a regular notice when complete information becomes available. The regular notice will cancel the (P) notice.
- c. When a change has taken place which is too complex to describe in a written notice, a (P) notice giving general information will be published. This notice will explain that follow up action will be taken to update charts by publishing patch corrections, new editions or new charts.

Please note that following the expiry of the 90-day comment or objection period, (P) notices describing proposed changes or intention to discontinue will be automatically cancelled. In the event of a change to these notices, a new Notice to Mariners will be issued.

Action Required on Receipt Of (T) & (P) Notices

It is not customary to make permanent corrections to charts and publications from (T) & (P) notices. On receipt of such notices, the information they contain should be noted in pencil on the affected charts and/or publications.

Caution

Mariners are reminded that charts and publications are not corrected from (T) & (P) notices when purchased from suppliers. For the list of charts affected by (T) & (P) notices, please refer to the index on page ii of this publication.

Table of Contents

Newfoundland and Labrador Coast **1**

Temporary Notices

*1111(T)/22	Seniartlit Islands to / à Nain – Waterway Information.....	1
-------------	--	---

Preliminary Notices

*206(P)/23	Great St. Lawrence Harbour and / et Lamaline Harbour – Aid to navigation to be Discontinued.....	1
*207(P)/23	Black Island to / à Little Denier Island – Fog Signal to be Discontinued	1
*410(P)/23	Tilt Cove and / et La Scie Harbour – Aid to Navigation to be Discontinued	2

Atlantic Coast **3**

Temporary Notices

*111(T)/21	Rivière des Prairies – Construction Operations.....	3
*206(T)/21	Plans, Baie des Chaleurs/Chaleur Bay (côte nord/north shore) – Federal Wharf Closed to Navigation	3
*318(T)/21	Pointe des Monts aux/to Escoumins – Scientific Moorings	3
*207(T)/22	Port de Québec – Obstruction	3
*209(T)/22	Rivière Ristigouche / Restigouche River – Federal Wharf Closed to Navigation.....	4
*307(T)/22	Port de Québec – Waterway Information.....	4
*411(T)/22	Lac Saint-Pierre – Obstruction: Floating and Falling Debris	4
*513(T)/22	Plans, Baie des Chaleurs/Chaleur Bay (côte nord/North Shore) – Federal Wharf Permanently Closed to Navigation.....	4
*709(T)/22	Port de Québec – Bridge Lights Temporarily Unlit	4
*809(T)/22	Port de Montréal – Waterway Information: Calculation of Under-Keel Clearance	5
*810(T)/22	Île du Petit Mécatina aux/to Îles Sainte-Marie – Waterway Information: Shoal	5
*811(T)/22	Cap-aux-Meules – Waterway Information: Restrictions	5
*1009(T)/22	Plans, Baie des Chaleurs/Chaleur Bay (côte nord/North Shore) – Waterway Information: Shallow Depths Reported	5
*1114(T)/22	Rivière-du-Loup – Waterway Information: Shallow Depths Reported	6
*1214(T)/22	Cap des Rosiers à/to Chandler – Obstruction: Sunken Barge and Excavator.....	6
*107(T)/23	Sable Island Bank / Banc de l'Île de Sable to / au St. Pierre Bank / Banc de Saint-Pierre – ODAS Buoy Unlit.....	6
*313(T)/23	Batiscan au/to Lac Saint-Pierre – Waterway Information: Shallow Depth Reported	6
*314(T)/23	Approaches to / Approches à Bay of Fundy / Baie de Fundy – Obstruction : Scientific Moorings.....	6
*315(T)/23	Georges Bank / Banc de Georges: Eastern Portion / Partie Est – Obstruction : Scientific Moorings.....	6
*316(T)/23	Havre de Gaspé – Caution Concerning Aquaculture Sites	7
*317(T)/23	Baie des Chaleurs / Chaleur Bay – Caution Concerning Aquaculture Sites.....	8
*318(T)/23	Plans, Baie des Chaleurs/Chaleur Bay (côte nord/North Shore) – Caution Concerning Aquaculture Sites	8

Preliminary Notices

*208(P)/23	Mahone Bay – Notice of Proposed Changes.....	9
*209(P)/23	Cape Tormentine à / to West Point – Unlit Buoy to be Discontinued.....	10
*210(P)/23	Détroit de Northumberland / Northumberland Strait: Partie Ouest / Western Portion: Ports / Harbours – Notice of Proposed Changes	11
*412(P)/23	Baie des Chaleurs / Chaleur Bay – Notice of Proposed Changes	13
*413(P)/23	Caraquet Harbour, Baie de Shippegan and / et Miscou Harbour – Notice of Proposed Changes	13
*414(P)/23	Plans Baie des Chaleurs / Chaleur Bay - Côte sud / South Shore – Notice of Proposed Changes	14

Inland Waters

15

Temporary Notices

*909(T)/14	Kingston Harbour and Approaches/et les approches – Dock Unserviceable	15
*1005(T)/15	Port Dalhousie – East and West Piers: Access Forbidden	15
*515(T)/16	Harbours on the East Shore of Lake Superior/Ports sur la rive est du lac Supérieur – Buoys Temporarily Discontinued	15
*814(T)/16	Main Duck Island to/à Scotch Bonnet Island – Partially Submerged Fixed Steel Barges	15
*1011(T)/16	Lake Ontario/Lac Ontario (Western Portion/Partie Ouest) – Silting Reported	16
*1218(T)/16	Hamilton Harbour – Silting Reported	16
*1219(T)/16	Toronto to/à Hamilton – Construction Operations	16
*108(T)/17	Harbours in Lake Erie/Havres dans le lac Érié – Unlit Buoys Temporarily Repositioned	16
*309(T)/17	Pelee Passage to/à la Detroit River – Low Water Levels Reported.....	17
*1206(T)/17	Lake Rosseau and/et Lake Joseph – Unlit Buoy Temporary Established	17
*709(T)/18	Kingston Harbour and Approaches/et les approches – Information Regarding Mooring and Anchoring	17
*710(T)/20	Murray Canal to Healey Falls Locks / Murray Canal aux Écluses de Healey Falls – Construction Operations	17
*1012(T)/20	Kingston Harbour and Approaches/et les approches – Construction Operations.....	18
*1210(T)/20	Demarcation Bay to/à Philips Bay – Mobile Offshore Drilling Unit Temporarily Established.....	18
*112(T)/21	Upper Gap to/à Telegraph Narrows – Construction Operations	18
*413(T)/21	Kingston Harbour and Approaches/et les approches – Aid to Navigation Temporarily Unlit	18
*810(T)/21	Fort Frances to/à Hostess Island and/et Sandpoint Island – Aids to Navigation Temporarily Discontinued	18
*907(T)/21	Lac des Deux Montagnes – Missing Unlit Buoy	19
*107(T)/22	Canal de la Rive Sud – Waterways Information	19
*108(T)/22	Lower Gap to/à Adolphus Reach – Construction Operations Frontenac II Ferry Dock .	19
*413(T)/22	Detroit River – Waterway Information: Bridge Construction.....	19
*614(T)/22	Canal de la Rive Sud – Bridge Repair Work.....	19
*615(T)/22	Canal de la Rive Sud – Bridge Demolition.....	20

*616(T)/22	Canal de la Rive Sud – Federal Wharf Permanently Closed to Navigation	20
*617(T)/22	Lac Saint-Louis – Aids to Navigation Temporarily Established	20
*618(T)/22	Point Clark to/à Southampton – Aids to Navigation Established.....	20
*1115(T)/22	Cape Hurd to/à Tobermory and/et Cove Island – Marine Works: Breakwater Construction	21
*109(T)/23	Port Hope Harbour – Dredging Operations	21
*415(T)/23	Toronto Harbour – Marine Works - Overhead Construction.....	21
<u>Preliminary Notices</u>		
*211(P)/23	Gull Harbour to/à Riverton – Aids to Navigation to be Discontinued.....	22
Pacific Coast		23
<u>Temporary Notices</u>		
No notices applicable for this edition.....		23
<u>Preliminary Notices</u>		
*212(P)/23	Shuswap Lake – Daybeacon to be Discontinued	23
Other (T) & (P) Notices		24
<u>Temporary Notices</u>		
*1105(T)/15	Canada – Safety of Offshore Exploration and Exploitation Vessels	24
*111(T)/23	Canadian Coast Guard – Automatic Identification System (AIS)	24
<u>Preliminary Notices</u>		
No notices applicable for this edition.....		25

List of Charts Affected by (T) & (P) Notices

Chart No.	Pages	Chart No.	Pages	Chart No.	Pages
1234	6	2067	16	4486	8
1236	3	2077	16	4522	2
1310	5	2085	21	4642	1
1312	4	2086	16	4864	1
1313	6	2123	17	4905	10
1316	3, 4	2181	16	4909	11, 12
1320	6	2274	21	4913	13
1429	19, 20	2291	20	4920	14
1430	20	2315	15	4921	3, 4, 5, 8
1509	3	3053	23	4956	5
1510	19	4011	6	5052	1
2006	18	4045	6	6022	17
2017	15, 17, 18	4255	6	6108	18
2018	19	4381	9, 10	6249	22
2021	17	4416	7	7661	18
2044	15	4426	4	14853 (U.S.)	19
2053	21	4468	5		
2060	15	4485	6		

Newfoundland and Labrador Coast

Temporary Notices

*1111(T)/22 Seniartlit Islands to / à Nain – Waterway Information

Reference chart: 5052

Tide Gauge 01430 located at Nain is undergoing maintenance. Observation and forecast data unavailable, however, prediction data still available.

(NW-N-1555-22)

Preliminary Notices

Atlantic Region

Comment Submission

Comments on proposed changes in preliminary (P) notices are solicited from mariners and other interested parties within three months of the initial publication date. Following this date, the notices will be cancelled. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

Comments should be directed to the following:

Superintendent,
Aids to Navigation & Waterways
Canadian Coast Guard, Atlantic Region
P.O. Box 1000
50 Discovery Drive
Dartmouth, NS B2Y 3Z8
Telephone: (506) 636-4708
Email: [DFO.CCGATLaidstoNavDiscont-
AidesalanavSupprATLGCC.MPO@dfo-mpo.gc.ca](mailto:DFO.CCGATLaidstoNavDiscont-AidesalanavSupprATLGCC.MPO@dfo-mpo.gc.ca)

*206(P)/23 Great St. Lawrence Harbour and / et Lamaline Harbour – Aid to navigation to be Discontinued

Reference chart: 4642

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
Granny Head Fog Signal	75.5	46° 51' 27.3"N 055° 44' 36.2"W

Initial publication date: Friday, February 24, 2023

[Comment submission deadline](#): Thursday, May 25, 2023

(N2023-003)

*207(P)/23 Black Island to / à Little Denier Island – Fog Signal to be Discontinued

Reference chart: 4864

The Canadian Coast Guard proposes to permanently discontinue the fog signal on the following aid to navigation:

Aid Name	LL #	Position
Surgeon Cove Point Light Station & Fog Signal	347	49° 31' 05.3"N 055° 07' 05.5"W

The light and structure to remain.

Initial publication date: Friday, February 24, 2023

[Comment submission deadline](#): Thursday, May 25, 2023

(N2022-306)

***410(P)/23 Tilt Cove and / et La Scie Harbour – Aid to Navigation to be Discontinued**

Reference chart: 4522

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
La Scie Harbour Floating Dock	267.2	49° 57' 35.4"N 055° 36' 05.6"W

Initial publication date: Friday, April 28, 2023

[Comment submission deadline](#): Thursday, July 27, 2023

(N2023-060)

Atlantic Coast

Temporary Notices

***111(T)/21 Rivière des Prairies – Construction Operations**

Reference chart: 1509

Repair work is taking place 24 hours a day at the Pie-IX bridge as of August 17th, 2020.

Buoys, jetties, and a turbidity curtain are in place.

(NW-Q-1112-20)

***206(T)/21 Plans, Baie des Chaleurs/Chaleur Bay (côte nord/north shore) – Federal Wharf Closed to Navigation**

Reference: Notice *1118/19 is cancelled.

Reference chart: 4921

The federal wharf at Chandler is closed to navigation. For safety reasons, it is not permitted to berth at the wharf.

For more information, please contact Mr. Simon Bilodeau at Transport Canada at 418-563-2325 or by email at the following address: simon.bilodeau@tc.gc.ca.

(NAVWARN NW-Q-1580-16)

***318(T)/21 Pointe des Monts aux/to Escoumins – Scientific Moorings**

Reference chart: 1236

Over 80 underwater scientific moorings have been placed in the area delimited by the following positions:

Pt 1:	49° 18' 00.7"N	067° 40' 03.6"W
Pt 2:	49° 18' 12.0"N	067° 43' 30.8"W
Pt 3:	49° 17' 31.3"N	067° 43' 32.4"W
Pt 4:	49° 17' 25.3"N	067° 40' 15.5"W

(NW-Q-0968-20)

***207(T)/22 Port de Québec – Obstruction**

Reference chart: 1316

Power boat 6 metres in length reported sunk at 46° 43.830'N 071° 20.000'W.

(NW-Q-1348-21)

***209(T)/22 Rivière Ristigouche / Restigouche River – Federal Wharf Closed to Navigation**

Reference: Notice 716(T)/19 is cancelled.

Reference chart: 4426

The federal wharf at Miguasha is closed to navigation. For reasons of safety and because of the collapsing risk, it is not permitted to berth at the wharf or to come closer than 20 metres from these structures.

For more information, please contact the regional representative of port operations at Transport Canada, Quebec region, M. Hugues Gagnon-Montreuil at 581-398-8378.

(NW-Q-0318-16)

***307(T)/22 Port de Québec – Waterway Information**

Reference chart: 1316

Repair work with scaffolding taking place on the Pierre-Laporte bridge Monday to Saturday. Bridge clearance reduced by 2.6 metres.

(NW-Q-0182-22)

***411(T)/22 Lac Saint-Pierre – Obstruction: Floating and Falling Debris**

Reference chart: 1312

Floating and falling debris reported beneath the bridge located at 46° 04.783'N 073° 09.205'W. The bridge is marked with yellow buoys suspended at mid-height between the deck and the water level. Warning signs installed above.

(NW-Q-1266-19)

***513(T)/22 Plans, Baie des Chaleurs/Chaleur Bay (côte nord/North Shore) – Federal Wharf Permanently Closed to Navigation**

Reference chart: 4921

The federal wharf in Paspébiac is permanently closed to navigation. For safety reasons, it is forbidden to moor there or drive in a vehicle.

For additional information, please contact the program officer responsible for Paspébiac port operations at Transport Canada, Mr. Hugues Gagnon-Montreuil at 418-398-8378 or TC.QUEPorts-PortsQUE.TC@tc.gc.

***709(T)/22 Port de Québec – Bridge Lights Temporarily Unlit**

Reference chart: 1316

The following four red lights, located on the Pierre-Laporte bridge, are temporarily unlit:

Pont Pierre-Laporte Northeast Light	46° 44.815'N 071° 17.480'W
Pont Pierre-Laporte Northwest Light	46° 44.809'N 071° 17.502'W
Pont Pierre-Laporte Southeast Light	46° 44.629'N 071° 17.368'W
Pont Pierre-Laporte Southwest Light	46° 44.622'N 071° 17.390'W

(NW-Q-1281-21, NW-Q-1282-21, NW-Q-1283-21, NW-Q-1284-21)

***809(T)/22 Port de Montréal – Waterway Information: Calculation of Under-Keel Clearance**

Reference chart: 1310

Canadian Coast Guard Marine Communications and Traffic Services has been using all Canadian Hydrographic Service water-level stations for the calculation of passage authorizations in the Sorel–Montreal sector of the navigational waterway, namely Sorel, Contrecoeur, Varennes, Montreal-Frontenac and Montreal-Jetty No. 1.

In light of the particular features of the navigational waterway in the portion between buoys M84 (downstream of the municipality of Verchères) and M157 (opposite to the Port of Montreal, section 109) as well as the No. 1 Anchorage Pointe-aux-Tremble, it was agreed to adjust upward the available water column by 10 cm in this portion.

The minimum water column in this portion of the navigational waterway as per the Varennes hydrographic station, obtained after adjustment, will be used for the calculation of under-keel clearance.

(NW-Q-0776-22)

***810(T)/22 Île du Petit Mécatina aux/to Îles Sainte-Marie – Waterway Information: Shoal**

Reference chart: 4468

Rocky shoal located at the entrance to Harrington Harbour. Navigation must take place between the wharf and the red lantern at 50° 29.832'N 059° 28.581'W.

(NW-Q-1494-20)

***811(T)/22 Cap-aux-Meules – Waterway Information: Restrictions**

Reference chart: 4956

Restrictions in place and mooring prohibited in certain areas at the fishermen's wharf, at the port of Cap-aux-Meules.

Contact the port manager for more information at 418-937-7635.

(NW-Q-0199-21)

***1009(T)/22 Plans, Baie des Chaleurs/Chaleur Bay (côte nord/North Shore) – Waterway Information: Shallow Depths Reported**

Reference chart: 4921

Shallower depths located at:

48° 24' 51.8"N	064° 23' 38.9"W	(2.9 metres)
48° 24' 52.7"N	064° 23' 41.9"W	(2.9 metres)
48° 24' 55.5"N	064° 23' 45.2"W	(2.5 metres)
48° 24' 53.7"N	064° 23' 43.7"W	(2.6 metres)

(NW-Q-1485-22)

***1114(T)/22 Rivière-du-Loup – Waterway Information: Shallow Depths Reported**

Reference: Notice 1008(T)/22 is cancelled.

Reference chart: 1234, 1320

Shallower depths located at:

47° 55' 29.8"N 069° 38' 57.7"W (9.7 metres)

47° 56' 58.4"N 069° 47' 24.2"W (3.2 metres)

48° 00' 07.0"N 069° 45' 43.1"W (8.5 metres)

(NW-Q-1058-22)

***1214(T)/22 Cap des Rosiers à/to Chandler – Obstruction: Sunken Barge and Excavator**

Reference chart: 4485

Sunken barge and excavator reported at 48° 35.1'N 064° 08.1'W. Barge is 18 metres by 7 metres.

(NW-Q-1709-22)

***107(T)/23 Sable Island Bank / Banc de l'Île de Sable to / au St. Pierre Bank / Banc de Saint-Pierre – ODAS Buoy Unlit**

Reference chart: 4045

ODAS buoy marked "44139" in 44° 14.400'N, 057° 06.180'W is unlit. Caution.

(NW-M-2321-22)

***313(T)/23 Batiscan au/to Lac Saint-Pierre – Waterway Information: Shallow Depth Reported**

Reference chart: 1313

A shallower depth of 10.6 metres is located at the following positions:

46° 19' 58.9"N 072° 32' 40.9"W

(NW-Q-1823-22)

***314(T)/23 Approaches to / Approches à Bay of Fundy / Baie de Fundy – Obstruction : Scientific Moorings**

Reference chart: 4011

Subsurface scientific equipment deployed in 42° 50.437'N 066° 43.862'W. Top of equipment is at 214 metres water depth.

(NW-M-0285-23)

***315(T)/23 Georges Bank / Banc de Georges: Eastern Portion / Partie Est – Obstruction : Scientific Moorings**

Reference chart: 4255

Subsurface scientific equipment deployed in 42° 18.196'N 065° 59.250'W. Top of equipment is at 234 metres water depth.

(NW-M-0284-23)

***316(T)/23 Havre de Gaspé – Caution Concerning Aquaculture Sites**

Reference chart: 4416

Vicinity	Positions	Description
L'Anse-aux-Cousins	48° 51' 21.2"N 064° 30' 02.6"W 48° 51' 06.2"N 064° 29' 25.6"W 48° 51' 00.2"N 064° 30' 02.6"W 48° 51' 00.2"N 064° 29' 30.6"W	Unmarked aquaculture site with submerged equipment.
Havre de Gaspé	48° 51' 50.2"N 064° 29' 02.5"W 48° 51' 20.2"N 064° 28' 37.5"W 48° 51' 20.2"N 064° 28' 16.5"W 48° 50' 47.2"N 064° 28' 16.5"W 48° 51' 23.2"N 064° 29' 40.5"W 48° 51' 23.2"N 064° 29' 20.5"W 48° 51' 30.2"N 064° 29' 02.5"W	Unmarked aquaculture site with submerged equipment.
Havre de Gaspé	48° 51' 18.5"N 064° 27' 02.5"W 48° 51' 08.8"N 064° 26' 34.6"W 48° 50' 51.1"N 064° 26' 35.4"W 48° 50' 47.2"N 064° 26' 45.5"W 48° 50' 47.2"N 064° 27' 02.5"W	Unmarked aquaculture site with submerged equipment, some of which is located outside the defined area.
Havre de Gaspé	48° 50' 25.7"N 064° 28' 24.5"W 48° 50' 51.2"N 064° 29' 28.7"W 48° 51' 03.8"N 064° 29' 16.1"W 48° 50' 37.7"N 064° 28' 12.6"W	Unmarked aquaculture site with submerged equipment.
Havre de Gaspé	48° 50' 47.2"N 064° 27' 07.5"W 48° 50' 38.6"N 064° 27' 07.5"W 48° 50' 29.4"N 064° 27' 34.1"W 48° 50' 44.9"N 064° 28' 11.5"W 48° 50' 47.1"N 064° 28' 11.3"W	Aquaculture site with non-compliant buoyage and equipment at the surface.
Havre de Gaspé	48° 51' 17.6"N 064° 28' 11.6"W 48° 51' 00.2"N 064° 28' 11.6"W 48° 51' 17.6"N 064° 27' 07.6"W 48° 51' 00.2"N 064° 27' 07.6"W	Aquaculture site with non-compliant buoyage with surface and submerged equipment.
Baie de Gaspé	48° 51' 21.2"N 064° 30' 02.6"W 48° 51' 06.2"N 064° 29' 25.6"W 48° 51' 00.2"N 064° 30' 02.6"W 48° 51' 00.2"N 064° 29' 30.6"W	Unmarked aquaculture site with submerged equipment.

(NW-Q-0732-16, NW-Q-0735-16, NW-Q-0737-16, NW-Q-0758-16,
NW-Q-0761-16, NW-Q-0794-16, NW-Q-1719-18)

***317(T)/23 Baie des Chaleurs / Chaleur Bay – Caution Concerning Aquaculture Sites**

Reference chart: 4486

Vicinity	Positions	Description
Cascapedia Bay	48° 07' 10.7"N 066° 01' 18.2"W 48° 07' 31.1"N 066° 00' 30.8"W 48° 07' 00.8"N 065° 59' 59.9"W 48° 06' 39.7"N 066° 00' 47.0"W	Aquaculture site with non-compliant buoyage with surface and submerged equipment.
Cascapedia Bay	48° 07' 22.0"N 065° 55' 12.0"W 48° 07' 22.0"N 065° 53' 14.0"W 48° 06' 33.0"N 065° 53' 14.0"W 48° 06' 33.0"N 065° 55' 12.0"W	Aquaculture site with non-compliant buoyage with submerged equipment.
Cascapedia Bay	48° 05' 24.2"N 066° 01' 42.8"W 48° 06' 11.2"N 066° 00' 07.8"W 48° 05' 36.2"N 065° 59' 29.8"W 48° 04' 49.2"N 066° 01' 04.8"W	Aquaculture site marked with non-compliant buoyage with surface and submerged equipment.
Tracadigache Bay	48° 05' 12.0"N 066° 12' 02.6"W 48° 05' 12.0"N 066° 11' 00.0"W 48° 04' 30.0"N 066° 11' 00.0"W 48° 04' 30.0"N 066° 12' 02.6"W	Aquaculture site with temporarily non-compliant buoyage.

(NW-Q-0769-16, NW-Q-0770-16, NW-Q-0783-16, NW-Q-0789-16)

***318(T)/23 Plans, Baie des Chaleurs/Chaleur Bay (côte nord/North Shore) – Caution Concerning Aquaculture Sites**

Reference chart: 4921

Vicinity	Positions	Description
Carleton-sur-Mer	48° 05' 21.9"N 066° 01' 55.5"W 48° 04' 45.0"N 066° 01' 15.3"W 48° 04' 21.7"N 066° 02' 11.5"W 48° 04' 56.2"N 066° 02' 51.2"W	Unmarked aquaculture site with submerged equipment.
Carleton-sur-Mer	48° 05' 50.6"N 066° 02' 27.5"W 48° 05' 29.7"N 066° 02' 04.7"W 48° 05' 04.8"N 066° 03' 00.7"W 48° 05' 25.6"N 066° 03' 23.5"W	Unmarked aquaculture site with submerged equipment.
Carleton-sur-Mer	48° 06' 14.9"N 066° 00' 02.5"W 48° 05' 39.1"N 065° 59' 22.1"W 48° 06' 28.1"N 065° 57' 41.7"W 48° 07' 02.8"N 065° 58' 21.3"W	Unmarked aquaculture site with submerged equipment.

(NW-Q-1716-18, NW-Q-1717-18, NW-Q-1718-18)

Preliminary Notices

Atlantic Region

Comment Submission

Comments on proposed changes in preliminary (P) notices are solicited from mariners and other interested parties within three months of the initial publication date. Following this date, the notices will be cancelled. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

Comments should be directed to the following:

Superintendent,
Aids to Navigation & Waterways
Canadian Coast Guard, Atlantic Region
P.O. Box 1000
50 Discovery Drive
Dartmouth, NS B2Y 3Z8
Telephone: (506) 636-4708
Email: DFO.CCGATLaidstoNavDiscont-AidesalanavSupprATLGCC.MPO@dfo-mpo.gc.ca

***208(P)/23 Mahone Bay – Notice of Proposed Changes**

Reference chart: 4381

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

Aid Name	LL #	Position	Proposed Changes
Fixed Aids			
Westhaver Island	451	44° 26' 09.8"N 064° 20' 15.3"W	Change aid structure. Change flash characteristics to: Fl 1 s; Ec 4 s.
Quaker Island	456	44° 30' 53.7"N 064° 13' 57.2"W	Change aid structure. Change flash characteristics to: Fl 2 s; Ec 4 s. Change lantern colour from red to white. Increase lantern intensity.
Floating Aids			
Coachman Ledge light and whistle buoy MA55	457	44° 30' 01.4"N 064° 10' 36.7"W	Discontinue the whistle. Change aid ID from MA55 to MJA. Change the function of the aid to North Cardinal. Change name to: "Coachman Ledge North Cardinal light buoy MJA". Increase lantern intensity. Change flash characteristics to: Fl 0.2 s; Ec 0.3 s.
Backman Island cautionary buoy MEA	5449.051	44° 24' 46.6"N 064° 17' 59.0"W	Reposition buoy to the following position: 44° 24' 46.9"N 064° 18' 02.5"W.
North Gooseberry shoal buoy MMC	5454.74	44° 31' 38.4"N 064° 16' 01.7"W	Change buoy type from spar to pillar.
Mahone Bay buoy MX51	5455.055	44° 32' 54.4"N 064° 11' 47.7"W	Discontinue buoy.
Mahone Bay buoy MX52	5455.06	44° 32' 48.4"N 064° 11' 44.7"W	Discontinue buoy.

Aid Name	LL #	Position	Proposed Changes
Mahone Bay buoy MX57	5455.08	44° 31' 23.0"N 064° 12' 18.0"W	Change the function of the aid to North Cardinal. Change aid ID from MX57 to MJB. Change name to: "Mark Island Bar North Cardinal light buoy MJB". Add white lantern with flash characteristics: Fl 0.3 s; Ec 0.7 s. Reposition buoy to the following position: 44° 31' 60.0"N 064° 12' 22.1"W.
Coachman Ledge buoy MD60	5464.01	44° 29' 18.4"N 064 10' 31.7"W	Change the function of the aid to South Cardinal. Change aid ID from MD60 to MP. Add white lantern with flash characteristics: (Q (6) + LFl) 15 s. Change name to: "Coachman Ledge South Cardinal light buoy MP".
Graves Shoal East Cardinal light buoy MXA	455.09	44° 32' 51.9"N 064° 11' 36.1"W	Establish an East cardinal buoy equipped with a white lantern with flash characteristics: Q(3) 10 s.

Initial publication date: Friday, February 24, 2023

[Comment submission deadline](#): Thursday, May 25, 2023

(F2022-021)

***209(P)/23 Cape Tormentine à / to West Point – Unlit Buoy to be Discontinued**

Reference chart: 4905

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
Shediac North Cardinal buoy XM	6103.1	46° 15' 42.0"N 064° 28' 12.0"W

Initial publication date: Friday, February 24, 2023

[Comment submission deadline](#): Thursday, May 25, 2023

(G2023-004)

***210(P)/23 Détroit de Northumberland / Northumberland Strait: Partie Ouest / Western
Portion: Ports / Harbours – Notice of Proposed Changes**

Reference chart: 4909

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

Aid Name	LL #	Position	Proposed Changes
Fixed Aids			
Shediac Wharf Light	1110.5	46° 14' 30.0"N 064° 31' 48.4"W	Change lantern colour from white to yellow. Change name to: "Pointe-du-Chene Wharf Light".
Pointe-du-Chene	1111.1	46° 14' 29.2"N 064° 31' 40.4"W	Decrease lantern intensity. Change flash characteristics to: Fl 1 s; Ec 4 s. Change name to: "Pointe-du-Chene Wharf Light".
Shediac Bay Yacht Club Breakwater	1111.5	46° 13' 41.2"N 064° 32' 49.5"W	Decrease lantern intensity. Change flash characteristics to: Fl 1 s; Ec 4 s. Change the period of service from "Year round" to "Seasonal".
Shediac 10 red stakes	6111.44	46° 13' 06.0"N 064° 33' 30.0"W	Discontinue 10 red stakes.
Shediac 10 green stakes	6111.49	46° 13' 06.0"N 064° 33' 30.0"W	Discontinue 10 green stakes.
Floating Aids			
Shediac light and bell buoy XN	1105	46° 16' 38.0"N 064° 29' 05.0"W	Discontinue the bell. Change name to: "Shediac light buoy XN".
Shediac light buoy XN18	1109	46° 15' 23.8"N 064° 31' 24.7"W	Reposition buoy to the following position: 46° 15' 23.2" N 064° 31' 23.6" W. Increase lantern intensity.
Shediac Harbour light buoy XN19	1109.2	46° 15' 17.2"N 064° 31' 26.1"W	Reposition buoy to the following position: 46° 15' 17.0" N 064° 31' 28.4" W. Decrease lantern intensity.
Shediac Harbour light buoy XP3	1109.81	46° 14' 29.8"N 064° 31' 39.2"W	Reposition buoy to the following position: 46° 14' 29.3" N 064° 31' 39.3" W. Change name to: "Pointe-du-Chene light buoy XP3".
Shediac Bay light buoy XN34	1111.2	46° 14' 21.5"N 064° 32' 24.0"W	Decrease lantern intensity.
Shediac Bay light buoy XN41	1111.45	46° 13' 50.0"N 064° 32' 44.5"W	Decrease lantern intensity.
Shediac Bay light buoy XN46	1111.48	46° 13' 41.6"N 064° 32' 53.6"W	Decrease lantern intensity.
Shediac Harbour buoy XP1	6109.805	46° 14' 29.8"N 064° 31' 39.7"W	Reposition buoy to the following position: 46° 14' 32.5" N 064° 31' 44.2" W. Add green lantern with flash characteristics: Fl 0.5 s; Ec 3.5 s. Change name to: "Pointe-du-Chene light buoy XP1".

Notices to Mariners – Monthly Summary of Temporary and Preliminary Notices
Atlantic Coast

Aid Name	LL #	Position	Proposed Changes
Shediac cautionary buoy XPA	6109.84	46° 14' 24.3"N 064° 31' 51.8"W	Discontinue buoy.
Shediac cautionary buoy XPC	6109.85	46° 14' 23.3"N 064° 31' 51.8"W	Discontinue buoy.
Shediac buoy XPD	6111.42	46° 16' 07.0"N 064° 33' 08.5"W	Change the function of the aid to Cautionary. Change name to: "Shediac Island cautionary buoy XPD".
Shediac buoy PLAS1	6111.43	46° 13' 16.4"N 064° 33' 20.2"W	Discontinue buoy.
Shediac buoy PLAS1	6111.455	46° 13' 23.6"N 064° 33' 15.3"W	Discontinue buoy.
Shediac buoy PLAS1	6111.47	46° 13' 22.3"N 064° 33' 16.3"W	Discontinue buoy.
Shediac buoy PLAS1	6111.54	46° 13' 15.1"N 064° 33' 18.8"W	Discontinue buoy.
Shediac buoy PLAS1	6111.55	46° 13' 18.6"N 064° 33' 20.1"W	Discontinue buoy.
Shediac buoy PLAS1	6111.56	46° 13' 21.1"N 064° 33' 19.7"W	Discontinue buoy.

Initial publication date: Friday, February 24, 2023

[Comment submission deadline](#): Thursday, May 25, 2023

(G2023-004)

***412(P)/23 Baie des Chaleurs / Chaleur Bay – Notice of Proposed Changes**

Reference chart: 4486

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

Aid Name	LL #	Position	Proposed Changes
Fixed Aids			
Blue Cove (Anse-Bleue) front range	1325	47° 49' 55.5"N 065° 04' 47.8"W	Change the aid type from front range to wharf light. Change lantern colour from red to green. Change flash characteristics to: Fl 1 s; Ec 5 s. Change the light operation from "Operates 24 h." to "Operates at night only." Change daymark colour to green and white.
Blue Cove (Anse-Bleue) rear range	1325.1	195° 04' 338.6 m from front	Change the aid type from rear range to landfall light. Change lantern colour from red to white. Change flash characteristics to: Fl 1 s; Ec 5 s. Change daymark colour to red, white and red.
Blue Cove (Anse-Bleue) Breakwater	1325.4	47° 49' 55.8"N 065° 04' 50.8"W	Change flash characteristics to: Fl 1 s; Ec 5 s. Add a red and white daymark.
Blue Cove (Anse-Bleue) Wharf	1325.5	47° 49' 53.7"N 065° 04' 48.8"W	Discontinue aid to navigation.

Initial publication date: Friday, April 28, 2023

[Comment submission deadline](#): Thursday, July 27, 2023

(G2023-016)

***413(P)/23 Caraquet Harbour, Baie de Shippegan and / et Miscou Harbour – Notice of Proposed Changes**

Reference chart: 4913

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

Aid Name	LL #	Position	Proposed Changes
Fixed Aids			
Caraquet Island	1322	47° 49' 21.2"N 064° 54' 16.0"W	Change flash characteristics to: Fl 1 s; Ec 5 s.
Maisonnette	1324	47° 50' 15.0"N 065° 00' 13.0"W	Change flash characteristics to: Fl 2 s; Ec 4 s. Change the light operation from "Operates 24 h." to "Operates at night only." Add a red, white and red daymark.

Initial publication date: Friday, April 28, 2023

[Comment submission deadline](#): Thursday, July 27, 2023

(G2023-016)

***414(P)/23 Plans Baie des Chaleurs / Chaleur Bay - Côte sud / South Shore – Notice of Proposed Changes**

Reference chart: 4920

The Canadian Coast Guard proposes to permanently change the following aids to navigation:

Aid Name	LL #	Position	Proposed Changes
Fixed Aids			
Petit Rocher	1339	47° 46' 54.6"N 065° 42' 27.2"W	Change lantern colour from white to red. Change flash characteristics to: Fl 1 s; Ec 5 s. Add a red and white daymark.
Petit-Rocher Breakwater light	1339.2	47° 46' 55.2"N 065° 42' 29.7"W	Increase lantern intensity.
Floating Aids			
Petit-Rocher light buoy ES2	1339.5	47° 46' 55.2"N 065° 42' 08.7"W	Increase lantern intensity.

Initial publication date: Friday, April 28, 2023

[Comment submission deadline](#): Thursday, July 27, 2023

(G2023-018)

Inland Waters

Temporary Notices

***909(T)/14 Kingston Harbour and Approaches/et les approches – Dock Unserviceable**

Reference chart: 2017

The Kingston psychiatric hospital dock is unserviceable and out of bounds for use as dockage until further notice.

(NOTSHIP C2409/10)

***1005(T)/15 Port Dalhousie – East and West Piers: Access Forbidden**

Reference chart: 2044

A recent engineering investigation identified structural issues and safety concerns with both the East and West piers at Port Dalhousie. In light of the inspection findings, the Department of Fisheries and Oceans is taking action to protect the safety of the public by prohibiting vessel, vehicular, and pedestrian access to the piers.

Vessels can still safely navigate the waters surrounding the piers, but will be unable to moor at the piers. The City of St. Catharines will accommodate boaters as possible at other local wharves.

Mark Sandeman
Area Manager, Client Services
Small Craft Harbours
Central & Arctic Region
Fisheries and Oceans Canada

3027 Harvester Road, Unit 310
Burlington, ON L7N 3G7
Telephone: (905) 639-2050
Facsimile: (905) 639-5975
Email: mark.sandeman@dfo-mpo.gc.ca

(NOTSHIP C567/15)

***515(T)/16 Harbours on the East Shore of Lake Superior/Ports sur la rive est du lac Supérieur – Buoys Temporarily Discontinued**

Reference chart: 2315

The Canadian Coast Guard has temporarily discontinued the following aids to navigation:
XT1, XT2, XT3, XT4, XT5, XT6, XT7, XT8, XT9, XT10, XT11, XT12.

(NOTSHIP C1045)

***814(T)/16 Main Duck Island to/à Scotch Bonnet Island – Partially Submerged Fixed Steel Barges**

Reference chart: 2060

There are 3 partially submerged fixed steel barges in North end of West Lake (43° 57' 02.3"N 077° 20' 12.8"W), which have been reported just below the water line.

Barges are marked with cautionary buoys.

(NOTSHIP C1641/14)

***1011(T)/16 Lake Ontario/Lac Ontario (Western Portion/Partie Ouest) – Silting Reported**

Reference chart: 2077

Silting reported in main entrance channel to Fifty Point Marina. Centre of channel depth reported to be 1.9 metres with shallower depths on the sides.

Mariners are requested to use caution in the area.

(NOTSHIP C2266/16)

***1218(T)/16 Hamilton Harbour – Silting Reported**

Reference chart: 2067

Silting reported along the North faces of Pier 11 and Pier 12:

Pier 11 North Face between positions 43° 16' 31"N 079° 50' 56"W and 43° 16' 29"N 079° 50' 49"W, and at position 43° 16' 28"N 079° 50' 42"W.

Pier 12 North Face between positions 43° 16' 27"N 079° 50' 39"W and 43° 16' 26"N 079° 50' 33"W.

Mariners are requested to use caution and reduce speed upon arrival and departure. Seaway draft will be affected when water level is less than 0.70 metres above chart datum in these areas.

(NOTSHIP C1831/13)

***1219(T)/16 Toronto to/à Hamilton – Construction Operations**

Reference chart: 2086

Construction operations taking place from November 14, 2016 until approximately 2026 at Lakeview Water Treatment Plant between Marie Curtis Park and Serson Creek. A variety of equipment will be used to expand the land mass along the shoreline. Landfill and 3 islands will be lit and marked.

(NOTSHIP C2533/16)

***108(T)/17 Harbours in Lake Erie/Havres dans le lac Érié – Unlit Buoys Temporarily Repositioned**

Reference chart: 2181

The following unlit spar buoys have been temporarily repositioned due to silting:

Aid Name	LL #	Temporary Changes
ES2	7169	Reposition to 42° 39' 10.0"N 081° 12' 32.0"W
ES3	7170	Reposition to 42° 39' 15.4"N 081° 12' 40.7"W
ES4	7171	Reposition to 42° 39' 16.8"N 081° 12' 37.7"W

The shallowest depth to 3.5M occurs between ES3 and ES4 with the deepest water off the red side of the channel. Mariners are requested to use caution in the area.

(B2017-003)

***309(T)/17 Pelee Passage to/à la Detroit River – Low Water Levels Reported**

Reference chart: 2123

Low water levels have been reported from the south end of the entrance to Sturgeon Creek Harbour northward.

Annette Winter
Project and Divestiture Officer
Small Craft Harbours
Fisheries and Oceans Canada

Canada Centre for Inland Waters (CCIW)
867 Lakeshore Road
Burlington, ON L7S 1A1
Telephone: (905) 315-5286
Email: annette.winter@dfo-mpo.gc.ca

(NOTSHIP C58/13)

***1206(T)/17 Lake Rosseau and/et Lake Joseph – Unlit Buoy Temporary Established**

Reference chart: 6022

The following unlit buoy has been temporary established:

Aid Name	LL #	Position
P3/1	9089.1	45° 08' 09.0"N 079° 40' 36.0"W

(D2017-006)

***709(T)/18 Kingston Harbour and Approaches/et les approches – Information Regarding Mooring and Anchoring**

Reference: Notice 309(T)/14 is cancelled.

Reference chart: 2017

All mooring or anchoring within the public port of Kingston is prohibited outside of designated marina areas until further notice without authorization from the port official.

Inquiries are to be directed to Transport Canada at (416) 952-0475.

***710(T)/20 Murray Canal to Healey Falls Locks / Murray Canal aux Écluses de Healey Falls – Construction Operations**

Reference chart: 2021

Construction operations, including diving operations, in progress as of July 6, 2020 between 1100 UTC and 0100 UTC at the mouth of the Trent River south of Dundas Street bridge in Trenton. The site is marked with red, green and white markers. Tug and barge on site, lit at night.

Vessels are advised to use caution when transiting the area and to keep clear of construction operations. Call 416-729-8830 for further details.

(NW-C-1012-20)

***1012(T)/20 Kingston Harbour and Approaches/et les approches – Construction Operations**

Reference chart: 2017

Wharf construction is taking place daily from 1100 UTC to 2300 UTC at the Kingston-Wolfe Island ferry terminal. The ferry remains operational. Vessels are not permitted to dock on the south side. The construction area is marked and lit.

(NW-C-1786-20)

***1210(T)/20 Demarcation Bay to/à Philips Bay – Mobile Offshore Drilling Unit Temporarily Established**

Reference: Notice 616(T)/07 is cancelled.

Reference chart: 7661

The unmanned mobile offshore drilling unit “SDC” continues to be temporarily established at 69° 24.71'N 138° 53.76'W. The structure is 202.4 metres long and 53 metres wide.

For information, contact Captain Connelly at 1-250-598-4513 or 1-250-744-9818 or e-mail at doncon@islandnet.com or dcmarine@shaw.ca.

***112(T)/21 Upper Gap to/à Telegraph Narrows – Construction Operations**

Reference chart: 2006

Construction operations are currently underway on the Bay of Quinte Skyway Bridge.

During these operations, lit barges are on site and the bridge clearance is 19 metres.

(NW-C-2834-19)

***413(T)/21 Kingston Harbour and Approaches/et les approches – Aid to Navigation Temporarily Unlit**

Reference chart: 2017

The following aid to navigation is temporarily unlit:

Marysville Wharf light (LL 399.3): 44° 11' 42.4"N 076° 26' 27.3"W

(NW-C-1802-20)

***810(T)/21 Fort Frances to/à Hostess Island and/et Sandpoint Island – Aids to Navigation Temporarily Discontinued**

Reference chart: 6108

The following aids to navigation are temporarily discontinued:

Aid Name	LL #	Position
Noden Causeway East	1465	48° 39' 08.5"N 093° 18' 47.6"W
Noden Causeway West	1466	48° 39' 08.5"N 093° 18' 49.1"W

(D2021-026T, 027T)

***907(T)/21 Lac des Deux Montagnes – Missing Unlit Buoy**

Reference chart: 1510

The following unlit buoy is currently missing and will not be replaced before the 2022 navigation season:

Aid Name	LL #	Position
Chenal Saint-Placide buoy HJ17	6251.68	45° 31' 20.7"N 074° 12' 25.1"W

(NW-Q-1526-20)

***107(T)/22 Canal de la Rive Sud – Waterways Information**

Reference chart: 1429

Inspection work taking place under the Champlain bridge Monday to Friday from 1000 UTC until 1900 UTC. Tug "Intense" and barge are on site and will be lit and marked at night. Tug "Intense" monitoring VHF channel 79.

(NW-Q-1179-20)

***108(T)/22 Lower Gap to à Adolphus Reach – Construction Operations Frontenac II Ferry Dock**

Reference chart: 2018

Construction operations are taking place daily during daylight hours at the Millhaven and Stella ferry docks. Temporary docks will be installed in the vicinity of the ferry docks. Docks will be marked with buoys and lit with amber lights.

(NW-C-2916-17)

***413(T)/22 Detroit River – Waterway Information: Bridge Construction**

Reference chart: 14853 (U.S.)

Bridge construction operations taking place in an area bounded by:

- 42° 17.200'N 083° 05.633'W
- 42° 17.183'N 083° 05.600'W
- 42° 17.067'N 083° 05.667'W
- 42° 17.000'N 083° 05.717'W
- 42° 17.017'N 083° 05.750'W
- 42° 17.100'N 083° 05.667'W

Unauthorized entry prohibited.

(NW-C-0151-22)

***614(T)/22 Canal de la Rive Sud – Bridge Repair Work**

Reference chart: 1429

Repair work in progress at the Honoré-Mercier Bridge (upstream) between Lasalle and Kahnawake. Bridge deck installed under the bridge span.

(NW-Q-1810-19)

***615(T)/22 Canal de la Rive Sud – Bridge Demolition**

Reference chart: 1429

Demolition work on the old Champlain Bridge in progress. Tugs, workboats, and barges on site.

(NW-Q-0204-21)

***616(T)/22 Canal de la Rive Sud – Federal Wharf Permanently Closed to Navigation**

Reference chart: 1429

The Lachine Port de Plaisance Marina is permanently closed. Services are no longer available to all pleasure crafts. Access to the navigational channel and canal is not affected.

Mooring prohibited.

(NW-Q-0356-22)

***617(T)/22 Lac Saint-Louis – Aids to Navigation Temporarily Established**

Reference chart: 1430

Six yellow lighted buoys marking a 400 metres breakwater awash temporarily established at the following coordinates:

45° 20' 44.5"N 073° 50' 32.9"W	45° 21' 00.3"N 073° 50' 11.6"W
45° 20' 47.7"N 073° 50' 29.4"W	45° 21' 05.4"N 073° 50' 07.6"W
45° 20' 50.0"N 073° 50' 24.1"W	45° 21' 11.8"N 073° 50' 04.6"W

(NW-Q-0579-22)

***618(T)/22 Point Clark to/à Southampton – Aids to Navigation Established**

Reference: Notice 1212(T)/21 is cancelled.

Reference chart: 2291

Twenty-two sub-surface moorings have been removed and replaced by spar buoys at the following coordinates:

44° 13.912'N 081° 37.060'W	44° 22.719'N 081° 32.404'W
44° 13.970'N 081° 37.379'W	44° 22.933'N 081° 33.992'W
44° 13.981'N 081° 38.188'W	44° 23.512'N 081° 31.893'W
44° 15.862'N 081° 36.683'W	44° 23.953'N 081° 32.850'W
44° 15.894'N 081° 37.028'W	44° 25.270'N 081° 29.521'W
44° 15.885'N 081° 37.468'W	44° 25.576'N 081° 30.070'W
44° 19.834'N 081° 36.316'W	44° 26.041'N 081° 30.817'W
44° 19.867'N 081° 36.618'W	44° 33.449'N 081° 19.640'W
44° 21.668'N 081° 34.609'W	44° 33.525'N 081° 19.847'W
44° 22.055'N 081° 34.987'W	44° 34.184'N 081° 21.275'W

(NW-C-0708-22)

***1115(T)/22 Cape Hurd to/à Tobermory and/et Cove Island – Marine Works: Breakwater Construction**

Reference chart: 2274

Little Tub Harbour breakwater rehabilitation works taking place Monday to Friday at 45° 15.348'N 081° 39.803'W since October 26, 2022.

(NW-C-1889-22)

***109(T)/23 Port Hope Harbour – Dredging Operations**

Reference: Notice 809(T)/18 is cancelled.

Reference chart: 2053

Dredging and wall repair operations in Port Hope Harbour. Entrance to the western basin is blocked. Caution.

***415(T)/23 Toronto Harbour – Marine Works - Overhead Construction**

Reference chart: 2085

Position : 43° 37' 44.3"N 079° 25' 04.3"W

Overhead construction taking place in the North Marina of Ontario Place between West Island and East Island. Waterway closed to marine traffic.

(NW-C-0064-23)

Preliminary Notices

Central Region

Comment Submission

Comments on proposed changes in preliminary (P) notices are solicited from mariners and other interested parties within three months of the initial publication date. Following this date, the notices will be cancelled. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

Comments should be directed to the following:

Superintendent, Mathieu Roy
Aids to Navigation & Waterways
Canadian Coast Guard, Central Region
1550 D'Estimauville Avenue
Québec, QC G1J 5E9
Telephone: (418) 648-7450
Email: mathieu.roy@dfo-mpo.gc.ca

No notices applicable for this edition.

Western Region

Comment Submission

Comments on proposed changes in preliminary (P) notices are solicited from mariners and other interested parties within three months of the initial publication date. Following this date, the notices will be cancelled. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

Comments should be directed to the following:

A/Superintendent, Marc Jourdenais
Aids to Navigation & Waterways
Canadian Coast Guard, Western Region
25 Huron Street
Victoria, BC V8V 4V9
Telephone: (250) 480-2602
Fax: (250) 480-2702
Email: marc.jourdenais@dfo-mpo.gc.ca

***211(P)/23 Gull Harbour to/à Riverton – Aids to Navigation to be Discontinued**

Reference chart: 6249

The Canadian Coast Guard proposes to permanently discontinue the following aids to navigation:

Aid Name	LL #	Position
Fixed Aids		
Hecla Island front range	1578	51° 00' 28.0"N 096° 45' 09.0"W
Hecla Island rear range	1579	001°00' 248.4 m from front
Floating Aids		
Hokanson Point buoy DC2	9805	50° 58' 50.0"N 096° 47' 12.0"W
Hokanson Point buoy DC4	9806	50° 58' 22.0"N 096° 47' 55.0"W

Initial publication date: Friday, February 24, 2023

Comment submission deadline: Thursday, May 25, 2023

(P2023-004)

Pacific Coast

Temporary Notices

No notices applicable for this edition.

Preliminary Notices

Western Region

Comment Submission

Comments on proposed changes in preliminary (P) notices are solicited from mariners and other interested parties within three months of the initial publication date. Following this date, the notices will be cancelled. Any objections raised must state the facts on which they are based and should include supporting information on safety, commerce and public benefit.

Comments should be directed to the following:

A/Superintendent, Marc Jourdenais
Aids to Navigation & Waterways
Canadian Coast Guard, Western Region
25 Huron Street
Victoria, BC V8V 4V9
Telephone: (250) 480-2602
Fax: (250) 480-2702
Email: marc.jourdenais@dfo-mpo.gc.ca

***212(P)/23 Shuswap Lake – Daybeacon to be Discontinued**

Reference chart: 3053

The Canadian Coast Guard proposes to permanently discontinue the following aid to navigation:

Aid Name	LL #	Position
Tappen Bay Starboard daybeacon	5686	50° 46' 38.0"N 119° 19' 24.0"W

Initial publication date: Friday, February 24, 2023

[Comment submission deadline](#): Thursday, May 25, 2023

(P2023-006)

Other (T) & (P) Notices

Temporary Notices

***1105(T)/15 Canada – Safety of Offshore Exploration and Exploitation Vessels**

Reference: Notice 410(T)/2007 is cancelled.

2015 Annual Edition of Notices to Mariners, Notice No. 20, pages A20-1 to A20-4.

Mariners are advised that offshore exploration and exploitation vessels may be conducting drilling operations in the following areas:

Gulf of St. Lawrence

NIL

Mainland NWT

NIL

Mackenzie Delta NWT/Beaufort Sea

NIL

Arctic Islands of the NWT/Arctic Islands of Nunavut

NIL

Eastern Arctic Offshore

NIL

Davis Strait

NIL

NOTE: Mariners are advised to obtain up-to-date position reports on drilling vessels and production installations before entering an area of exploration and exploitation. This information is available by contacting, as appropriate, ECAREG CANADA, NORDREG CANADA or CVTS OFFSHORE via any Marine Communications and Traffic Services Centre (MCTS).

(NOTSHIP M2215/15) (NEB)

***111(T)/23 Canadian Coast Guard – Automatic Identification System (AIS)**

Reference: Notice *208(T)/21 is cancelled.

AIS Aids to Navigation (AtoNs)

Mariners are advised that the Canadian Coast Guard (CCG) is continuing to conduct supervised test beds of AIS AtoNs, with the objective of bringing AIS AtoNs to Full Operational Capability (FOC). Specific information on AIS AtoN test bed sites can be found on the CCG e-Navigation Maritime Information Portal at <https://e-navigation.canada.ca/topics/aids/docs/ais-aton/locations-en>.

Although AIS was originally developed as a collision avoidance tool for vessels, it also allows for the broadcasting of other types of data, such as the AIS AtoN “Message 21” (AIS AtoN Report).

Ships need to be equipped with standard shipborne AIS equipment for the display of AIS messages. The IMO mandatory carriage requirement for the Class “A” AIS display is the Minimum Keyboard Display (MKD), however, the display and use of the AtoN information may require additional hardware and/or software such as an AIS-connected Electronic Chart Display and Information System (ECDIS), Electronic Chart System (ECS), Radar or Portable Pilot Unit (PPU).

As the AIS information available to mariners will be dependent on their display system and its compliance with the latest IMO and IALA standards, some transmitted information may not be displayed or may have a different symbol. Mariners are encouraged to install and upgrade systems that provide AIS overlay on ECDIS, ECS and/or Radar. Mariners should be familiar with the display settings on their vessel's shipborne equipment.

All geographical positions (latitude and longitude) are based on the WGS 84 datum; time is displayed in Coordinated Universal Time (UTC).

CCG is making every effort to broadcast quality information; however, as with any navigational tool, mariners should not rely on this information as their sole means of navigation.

Mariners are advised to consult the CCG e-Navigation web page on AIS AtoN, accessible at <https://e-navigation.canada.ca/topics/aids/docs/ais-aton/index-en> for pertinent information, including examples of AIS AtoN display and symbology.

Individual NAVWARNs and/or NOTMARs are rarely issued for AIS AtoN trials.

Mariners are requested to provide feedback on the AIS AtoN test beds to the CCG e-Navigation Team at ccg.enav.gcc@dfo-mpo.gc.ca. In addition, mariners who wish to participate in CCG's questionnaire on AIS AtoN are invited to access it at <https://e-navigation.canada.ca/docs/surveys/asm-aton-en>. The collected results will guide the CCG in further developing this information service.

Preliminary Notices

No notices applicable for this edition.